



BMW 2 ACTIVE TOURER:

Vinnumber:	WBA6T510X0VE73940	Versionname:	216d (85kW)
First Registrationdate:	21/11/2018	Fiscalpower:	
Expertise Mileage:	127054	Power Kw:	85
Bodytype:		Body colour	Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	3327
Fueltype:	Diesel		
Maintenance	OK		
Maintenance	over 10000 km		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	1	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar fixed
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Tyres

	205/60/16/96 H			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Semperit: 5 mm	Re.R.	Semperit: 5 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/60 R 16 96 H
Tyre size FR				205/60 R 16 96 H
Tyre size RL				205/60 R 16 96 H
Tyre size RR				205/60 R 16 96 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				2477
Tyre make RR				2477

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1147,68
Ignition key, Missing, Replace	350,09



Interior, Dirty, Forfeit

100,00



Gear shift lever knob, Worn, Acceptable

0,00



Windscreen, Stone chip(s), Windscreen repair

75,44



Windscreen, Stone chip(s), Acceptable

0,00



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------



Bumper F, Stone chip(s), Acceptable	0,00
-------------------------------------	------



Step L, Scratch(es), Acceptable	0,00
---------------------------------	------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Wing RL, Dent(s), Acceptable	0,00
------------------------------	------



Alloy rim FL, Scratch(es), Repair and paint (complete)	133,03
--	--------





Boot cover, Scratch(es), Acceptable	0,00
-------------------------------------	------



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)	356,09
--	--------



Wing RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim FR, Scratch(es), Repair and paint (complete)	133,03
--	--------



Step R, Scratch(es), Acceptable	0,00
---------------------------------	------



Door RR, Dent(s) and scratch(es), Acceptable	0,00
--	------



Roof, Scratch(es), Acceptable	0,00
-------------------------------	------

