SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Marcel Peeters

2-FHV-919

2-FHV-919 · ST Line 1.0i EcoBoost 125pk M6 · 4 November 2026 · Zaventem Brussel

Specifications

License Plate Number	2-FHV-919
Manufacturer	FORD
Model	Puma
Model Versions	ST Line 1.0i EcoBoost 125pk M6
Body Type	5 door hatchback
Color	Darkgrey
Paint Type	Metallic
Production Year	2024
KW	92
Fuel Type	Gasoline

VIN	WF02XXERK2RG48548
Cylinder Capacity	999 cm3
Transmission Type	Handmatig geschakelde transmissie6
First Admission	16-05-2024
First Registration	16-05-2024
Odometer	77.276 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	5

Images



























1 3 5
2 4 6 R







Accessories

ABS	Electric windows front
Airbags	Electrically adjustable exterior mirrors
Alloy wheels	Fog lights
Audio System	Leather steering wheel
Automatic air conditioning	Navigation system
Bluetooth car kit	Rear parking sensors
Central door locking	Seat heating
Centre armrest	Steering wheel multifunction
Cruise control	Steeringwheel – Heated
Electric rear windows	Windscreen – Heated

Condition

Condition exterior	Adequate	Last Maintenance	Unknown
Condition interior	Adequate	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	3 mm	Continental	215 mm	55 mm	17 inch	Summer
Rear Left	4 mm	Continental	215 mm	55 mm	17 inch	Summer
Front Right	3 mm	Continental	215 mm	55 mm	17 inch	Summer
Rear Right	4 mm	Continental	215 mm	55 mm	17 inch	Summer
Spare Tire Type	Compressor					

Damages




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Small dent(s)	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Overfender	Scratch(es)	Spray	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Reardoor – Left	Scratch(es)	Stootlijst	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	small dents / small scratches	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Left Front	Damaged	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Front	Damaged	Rim repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Dent(s)	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Drivers seat	Stains & dirt	Cleaning	No



Acceptable