MACADAM










Renault Clio: N012JS

Vinnumber:	**VF1RJA00268113466**	Versionname:	**Clio 1.0 TCe 74kW Bi-Fuel Intens**
First Registrationdate:	**29/10/2021**	Fiscalpower:	
Expertise Mileage:	**103612**	Power Kw:	**74**
Bodytype:		Body colour	**Blanc Glacier niet-metaallak**
Gearbox:	**MAN 6 VIT**	Paint type	**Opaque**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Petrol**	Parking lot	**1159**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**Yes**		

Options

Number of keys total	**2**	Lining semi-leather	
GPS		Rear parking sensors	
Autom climate control		Hook	
Radio multimedia		Rear view camera	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 45 / 17 / 88 / W / Aluminium	6,4 mm	Hankook	Summer
	Right	205 / 45 / 17 / 88 / W / Aluminium	6,4 mm	Hankook	Summer
Rear	Left	205 / 45 / 17 / 88 / W / Aluminium	7,0 mm	Hankook	Summer
	Right	205 / 45 / 17 / 88 / W / Aluminium	7,2 mm	Hankook	Summer

Assistance equipment

Service, Maintenance, Execute



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)





Windscreen, Stone chip(s), Windscreen repair




Wing RR, Dent(s) and scratch(es), Repair and paint (complete)





Outside rear-view mirror housing R, Scratch(es), Replace and paint




Rear spoiler, Scratch(es), Repair and paint (complete)




Onderhoudshistorie van: VF1RJA00268113466

ALPHABET

Kenteken	N012JS
Merk Model	Renault Clio 1.0 TCe 74kW Bi-Fuel Intens
Brandstofsoort	LPG
Datum deel1	10/29/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
10/14/25	94,635	APK
10/14/25	94,635	Bougie
10/14/25	94,635	Luchtfilter
10/14/25	94,635	Onderhoudsbeurt
10/14/25	94,635	Remblokken achterzijde
9/5/25	91,697	LPG afstellen/ inleren
11/25/24	82,983	CNG gasdrukregelaar
10/21/24	81,422	APK
10/21/24	81,422	Onderhoudsbeurt
10/21/24	81,422	Ruitenwisserblad(en) voorzijde
7/6/24	0	Accu
1/25/24	61,573	Accu
10/23/23	54,233	Bougie
10/23/23	54,233	Luchtfilter
10/23/23	54,233	Onderhoudsbeurt
10/23/23	54,233	Sleutelbatterij
10/21/22	28,344	LPi filter
10/21/22	28,344	Onderhoudsbeurt