




1.0 EcoBoost 125pk ST Line X Business · 8 June 2026 · Schiphol

Specifications

		Cylinder Capacity	999 ^{cm³}
Manufacturer	FORD	Transmission Type	Handmatig geschakelde transmissie6
Model	Focus	MOT	01-11-2026
Model Versions	1.0 EcoBoost 125pk ST Line X Business	First Admission	01-11-2022
Body Type	5 door hatchback	First Registration	01-11-2022
Color	Black	License Plate 1a Available	
Paint Type	Metallic	VAT/Marge	BTW
Production Year	2022	Odometer	145.638 ^{Km}
KW	91	Numer Of Keys	1
Fuel Type	Gasoline	Interior	Darkgrey - Cloth
VIN	WF0NXXGCHNNB06805	Number Headrests	5

Images





Accessories

ABS	Electrically adjustable & heated exterior mirrors
Airbags	ESP
Alloy wheels	Fog lights
ASR	Front & rear parking sensors
Audio System	Leather steering wheel
Automatic air conditioning	Navigation system
Bluetooth car kit	Rear view camera
Central door locking	Roller cover / parcel shelf
Centre armrest	Seat heating
Cruise control	Steering wheel multifunction
Dimming interior mirror	Steeringwheel - Heated
Electric rear windows	Windscreen - Heated
Electric windows front	

Condition

Condition exterior	Adequate	Last maintenance odometer	110.000
Condition interior	Adequate	Previous Repairs	Unknown
Last Maintenance	15-11-2025		

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	3 ^{mm}	Vredestein	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Left	4 ^{mm}	Vredestein	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Front Right	3 ^{mm}	Vredestein	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Right	4 ^{mm}	Vredestein	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Spare Tire Type	Homecomer					
Spare Tire Profile	5 ^{mm}					

Damages




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Missing	Reservesleutel manco	Replace	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Interior	Worn	Vloerbekleding linksvoor gaten	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Small scratch(es)	Acceptable	Yes



Damage Part

Damage Type

Repair Type


Acceptable

Reardoor - Right

Scratch(es)

Polish

No



Damage Part

Damage Type

Notes

Repair Type

Acceptable

Fender - Rear Right

Small scratch(es)

Wielkuiprand

Spotrepair

No



Damage Part

Damage Type

Repair Type

Acceptable

Alloy - Right Rear

Scratch(es)

Rim repair

No



Damage Part

Roof

Damage Type

Dent(s)

Repair Type

Restyle

Acceptable

No



Damage Part

Co drivers seat

Damage Type


Stains & dirt

Repair Type

Cleaning

Acceptable

No



Damage Part

Alloy - Right Front

Damage Type

Small scratch(es)

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Damage Type

Notes

Repair Type

Acceptable

Hood

Small dent(s)

Rand voorzijde doorgezet

Restyle

No



Damage Part

Notes

Repair Type

Acceptable

Fender - Front Left

Badge

Replace

No



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Front Left

Dent(s)

Panelbeating & Spray

No