DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	JMZKBAC33 0A364158	Mileage	52 106 km	Engine (Fuel) Type	Hybrid petrol
Licence Plate	2GAS941	Registration date	09/10/2024	Engine size	1490
Brand	MAZDA	Fuel level	-	Transmission	Automatic
Model	2-Hybrid-Berlina-KBAC3-2021	Car type	PC	Gears	-
Body Type	SUV CrossOver	Number of seats	-	Condition of the car	Unknown
Doors	5	Exterior Color	Noir		

Inspection Details

Inspection date	04/11/2026	Inspection loc.	AVIS Own Risk - Parc AVIS	Fleet owner	AVIS Own Risk Belgique



Other technical information


Refill emergency kit	✓	Adapter USB	✓
Rear parcel shelf	✓	Service manual holder	✗
Emergency compressor kit	✗	User manual	✗

Options / Equipment

Tyres

Bridgestone 195/55/16 V Summer 5.0 mm

Bridgestone 195/55/16 V Summer 5.0 mm



Bridgestone 195/55/16 V Summer 5.0 mm

Bridgestone 195/55/16 V Summer 5.0 mm



Damages

1



Part	Rear parcel shelf retaining strap
Position	Back right
Damages	Missing
Severity	-
Repair mode	Replace

2



Part	Emergency compressor kit
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

3



Part	Engine soundproofing
Position	-
Damages	Perforated
Severity	-
Repair mode	Replace

4



Part	Door
Position	Front left
Damages	Dented
Severity	-
Repair mode	Smart Repair
	x3

DEKRA

DEKRA Automotive Solutions

Appraisal Report

5



Part	Wing
Position	Back left
Damages	Dented
Severity	-
Repair mode	For info

x2

6



Part	Spoiler
Position	Back
Damages	Dent & Chips
Severity	-
Repair mode	Replace

7



Part	Bumper
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Smart Repair

8



Part	Service manual holder
Position	-
Damages	Missing
Severity	-
Repair mode	For info

9

Part	User manual
Position	-
Damages	Missing
Severity	-
Repair mode	For info