



HYUNDAI TUCSON: GR-884-KE

Vinnumber:	TMAJC811BPJ222946	Versionname:	HYUNDAI TUCSON 1.6 HYBRID 230 BUSINESS VP
First Registrationdate:	25/09/2023	Fiscalpower:	[5P] bva 6-230CH-10cv (SUV)
Expertise Mileage:	168118	Power Kw:	169
Bodytype:	SUV	Body colour:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Black
Fueltype:	Hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
GPS storage		Headlights Xenon/LED/Laser	
GPS storage	HD	Rear parking sensors	
Windows electric F		Rear view camera	
Windows electric R		Seat cover lining	Lining Other
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

	215/65/17/103 H			
Winter tyres:	Fr.L.	Firestone: 70%	Fr.R.	Firestone: 65%
	Re.L.	Firestone: 30%	Re.R.	Firestone: 35%
Tyre profile depth FL				3.7
Tyre profile depth FR				4.1
Tyre profile depth RL				6.1
Tyre profile depth RR				6.0
Tyre size FL				215/65 R 17 103 H
Tyre size FR				215/65 R 17 103 H
Tyre size RL				215/65 R 17 103 H
Tyre size RR				215/65 R 17 103 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				258
Tyre make FR				258
Tyre make RL				258
Tyre make RR				258

Assistance equipment

Seat cover FR, Dirty, Cleaning



Tyre FR, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Tyre FL, Out of tolerance, Replace



Tyre RL, Out of tolerance, Replace



Alloy rim RL bitone/polychrome, Scratch(es), Acceptable



Wing FL, Dent(s), Repair and paint (complete)



Door RL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Paint



Wing trim RR, Scratch(es), Replace



Door trim RR, Scratch(es), Replace



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Luggage compartment cover, Tear, Repair/replace (lump sum)



Boot lid covering R, Scratch(es), Replace



Historique Maintenance

Immatriculation: GR-884-KE Date de 1ère immatriculation: 25/09/2023

Modèle: Hyundai TUCSON 1.6 HYBRID 230 BUSINESS VP [5P] bva 6-230CH-10cv (SUV)

Date	Kilométrage	Fournisseur	Descriptif
06/08/2026	163.342	DELHORBE AUTO HYUNDAI REIMS	LIQUIDE DE FREIN
			REVISION ET CLIM
26/02/2026	147.052	DELHORBE AUTO DIFFUSION	REVISION
06/01/2026	139.895	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS HIVER
28/11/2025	134.830	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
05/11/2025	131.129	DELHORBE AUTO DIFFUSION	LIQUIDE DE FREIN
			FILTRE A AIR RPLT
			REVISION ET CLIM
20/06/2025	109.786	DELHORBE AUTO DIFFUSION	BALAI ESSUIE GLACE AR
			REVISION
			COURROIE ACCESSOIRES RPLT
28/03/2025	92.963	J.P. FROMENT	BOITIER D ALLUMAGE RPLT
			REVISION ET CLIM
20/03/2025	90.221	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
11/12/2024	72.769	J.P. FROMENT	LIQUIDE DE FREIN
			REVISION ET CLIM
			FILTRE A AIR RPLT
			BALAI ESSUIE GLACE AV
25/11/2024	69.035	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
16/09/2024	59.856	DELHORBE AUTO DIFFUSION	PURGE CIRCUIT FREIN CTRL
			REVISION ET CLIM
27/05/2024	33.889	J.P. FROMENT	LIQUIDE DE FREIN
			REVISION ET CLIM
13/02/2024	15.409	J.P. FROMENT	REVISION
01/12/2023	4.875	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS HIVER