



Polestar 2 (UKL): 2CHN914

Vinnumber:	LPSVSEDEENL081549	Versionname:	Polestar 2 78kWh Dual Motor Long Range 408pk/cv
First Registrationdate:	1/08/2022	Fiscalpower:	5p
Expertise Mileage:	162935	Power Kw:	69
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Electric		
Maintenance	OK		
Maintenance	plus 19268 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Maintenance book present		
Type of GPS storage	HD		


Tyres

	245/40/20/99 Y			
Summer tyres:	Fr.L.	Firestone: 5 mm	Fr.R.	Firestone: 5 mm
	Re.L.	Firestone: 4 mm	Re.R.	Firestone: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				4.0
Tyre profile depth RR				5.0
Tyre size FL				245/40 R 20 99 Y
Tyre size FR				245/40 R 20 99 Y
Tyre size RL				245/40 R 20 99 Y
Tyre size RR				245/40 R 20 99 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				258
Tyre make FR				258
Tyre make RL				258
Tyre make RR				258

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

MOT certificate, Missing, Replace



Windscreen, Stone chip(s), Replace



Alloy rim FL polished, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable




Alloy rim RR polished, Scratch(es), Repair and paint (complete)




Door RR, Dent(s) and scratch(es), Acceptable



Door FR, Dent(s), Acceptable



Alloy rim FR polished, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Kenteken	2CHN914
Merk Model	Polestar Polestar 2 78kWh Dual Motor Long Range 408pk/cv 5p
Brandstofsoort	Elektrisch
Datum deel1	8/1/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
4/1/26	152,203	ruitenwisserrubber vooraan	Vervangen
4/1/26	152,203	Volvo motorolie service	Uitvoeren
10/27/25	133,762	koelwatervloeistof	Bijvullen/-laden
7/23/25	121,328	klein materiaal	
7/23/25	121,328	remvloeistof	Vervangen
7/23/25	121,328	ruitenwisserrubber vooraan	Vervangen
7/23/25	121,328	Volvo motorolie service	Uitvoeren
10/15/24	90,164	parkeersensor vooraan	Vervangen
10/15/24	90,164	ruitenwisserrubber vooraan	Vervangen
10/15/24	90,164	ruitenwisservloeistof	Bijvullen/-laden
10/15/24	90,164	Volvo motorolie service	Uitvoeren
2/1/24	59,279	klein materiaal	Uitvoeren
2/1/24	59,279	ruitenwisserrubber vooraan	Vervangen
2/1/24	59,279	Volvo motorolie service	Uitvoeren