DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	WBA11EE03 05427339	Mileage	31 515 km	Engine (Fuel) Type	Petrol
Licence Plate	2HKU927	Registration date	14/08/2025	Engine size	1499
Brand	BMW	Fuel level	-	Transmission	Automatic
Model	X1-2022	Car type	PC	Gears	-
Body Type	SUV CrossOver	Number of seats	-	Condition of the car	Unknown
Doors	5	Exterior Color	Vert		

Inspection Details

Inspection date	04/11/2026	Inspection loc.	AVIS Own Risk - Parc AVIS	Fleet owner	AVIS Own Risk Belgique



Other technical information


Emergency compressor kit	✓	Service manual holder	✓
Refill emergency kit	✓	User manual	✓
Rear parcel shelf	✓	Adapter USB	✓

Options / Equipment

Tyres

Nexen 225/55/18 Y Summer 5.0 mm

Nexen 225/55/18 Y Summer 5.0 mm



Nexen 225/55/18 Y Summer 5.0 mm

Nexen 225/55/18 Y Summer 5.0 mm

Damages

1



Part	Bumper
Position	Front
Damages	Dented
Severity	-
Repair mode	Repair

2



Part	Bumper grille
Position	Front
Damages	Scratched
Severity	-
Repair mode	Replace

3



Part	Door
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Repair