



Volkswagen Touran (UKL): 2CKX197

Vinnumber:	WVGZZZ1T9PW000320	Versionname:	Touran Highline 2.0TDi 150pk/cv 5p DSG7
First Registrationdate:	30/08/2022	Fiscalpower:	
Expertise Mileage:	114902	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar removable
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/60/16/96 V				
Summer tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/60 R 16 96 V
Tyre size FR				205/60 R 16 96 V
Tyre size RL				205/60 R 16 96 V
Tyre size RR				205/60 R 16 96 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	-----	------------	-----

Seat cover FR, Stain, Cleaning



Door RL, Dent(s), Acceptable



Boot carpet, Stain, Cleaning



Internal boot lining R, Scratch(es), Smart repair



Internal boot lining L, Scratch(es), Smart repair



Boot lid covering R, Scratch(es), Smart repair



Tailgate / Boot, Dent(s), Acceptable



Bumper R, Scratch(es), Acceptable



Wing FR, Dent(s) and scratch(es), Acceptable



Kenteken	2CKX197
Merk Model	Volkswagen Touran Highline 2.0TDi 150pk/cv 5p DSG7
Brandstofsoort	Diesel
Datum deel1	8/30/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
5/7/26	111,210	klein materiaal	
5/7/26	111,210	remblokken achter	Vervangen
5/7/26	111,210	remschijven en blokken vooraan	Vervangen
7/29/25	90,142	brandstof hoofdfilter	Vervangen
7/29/25	90,142	Inspectie met olie vervanging (vast in	Uitvoeren
7/29/25	90,142	klein materiaal	
7/29/25	90,142	remvloeistof	Vervangen
7/29/25	90,142	ruitenwisservloeistof	Bijvullen/-laden
3/17/25	78,279	controle niveaus	Uitvoeren
3/17/25	78,279	diagnose	Uitvoeren
3/17/25	78,279	klein materiaal	
3/17/25	78,279	koelwatervloeistof	Bijvullen/-laden
9/4/24	64,345	batterij	Vervangen
9/4/24	64,345	Inspectie met olie vervanging (vast in	Uitvoeren
9/4/24	64,345	klein materiaal	
9/4/24	64,345	koelwatervloeistof	Bijvullen/-laden
9/4/24	64,345	luchtfiler interieur	Vervangen
9/4/24	64,345	remblokken achter	Vervangen
9/4/24	64,345	ruitenwisservloeistof	Bijvullen/-laden
1/31/24	46,601	controle niveaus	Uitvoeren
1/31/24	46,601	klein materiaal	
1/31/24	46,601	ruitenwisservloeistof	Bijvullen/-laden
10/5/23	34,023	klein materiaal	
10/5/23	34,023	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
10/5/23	34,023	ruitenwisserrubber achter	Vervangen
10/5/23	34,023	ruitenwisserrubber vooraan	Vervangen
9/8/23	31,699	controle niveaus	Uitvoeren
9/8/23	31,699	klein materiaal	
12/1/22	10,312	controle niveaus	Uitvoeren