
MACADAM







BMW 220i Coupe: SIRAC

Vinnumber:	**WBA11CM0908C44583**	Versionname:	
First Registrationdate:	**27/06/2023**	Fiscalpower:	
Expertise Mileage:	**93641**	Power Kw:	
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**NOT OK**		
Maintenance	**min 1300 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		
Registration Certificate Home (BE)	**Yes**		

Options

Number of keys total	**2**	Type of Tow bar	**No Tow bar**
GPS			
Type of headlighting	**Headlighting LED**		
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**225/40/19/93 Y**			
	Fr.L.	**Pirelli: 5 mm**	Fr.R.	**Pirelli: 5 mm**
	Re.L.	**Hankook: 4 mm**	Re.R.	**Hankook: 4 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**225/40 R 19 93 Y**
Tyre size FR	**245/35 R 19 93 Y**
Tyre size RL	**245/35 R 19 93 Y**
Tyre size RR	**245/35 R 19 93 Y**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**264**
Tyre make FR	**264**
Tyre make RL	**260**
Tyre make RR	**260**

Assistance equipment

Number of charging cables (normal)	**0**
Number of charging cables (rapid charge)	**0**

Service, Maintenance, Execute



Bumper F, Scratch(es), Repair and paint (complete)











Bonnet, Dent(s), Acceptable

Alloy rim FL, Scratch(es), Repair and paint (complete)






Door FL, Scratch(es), Acceptable




Door FL, Repaired, Check




Wing RL, Repaired, Check




Bumper R, Scratch(es), Acceptable




Bumper trim R, Dent(s), Replace





Alloy rim RR, Scratch(es), Repair and paint (complete)




Tyre RR, Tear, Replace





Door FR, Scratch(es), Acceptable




Sill trim R, Scratch(es), Acceptable




Door FR, Repaired, Check





Alloy rim FR, Scratch(es), Repair and paint (complete)






Wing FR, Repaired, Check




Bodywork, Paint measurement, Check

