

## Expertise

Protocol number: 46108230  
Order No. / Reference: 26558622  
Inspection date: 23 Jun 2026

Manufacturer: Renault

Model: Twingo Electric ZEN

VIN: VF1AH000969276659



### Vehicle details

#### Manufacturer / Type / Model / Equipment

Renault Twingo Electric ZEN

**Vehicle Identification number** VF1AH000969276659

**Mileage (Read)** 45,856 km

**First registration** 16 May 2022

**Number of holders** 1

**Power / Engine displacement** 31 kw / 0 ccm

**Fuel type / Cylinder** Electric / 0

**Gearbox / Number of gears** Direct drive / 1

**Type of drive** Front drive

**Type of vehicle** Saloon car

**Colour / colour code** Pyrénées-Weiß

**Doors / Seats** 5 / 5

**Upholstery type** Cloth

**Colour of upholstery** Black-Grey



## Vehicle details

|  |                                |                                |  |
|--|--------------------------------|--------------------------------|--|
| <b>Maintenance booklet / proof</b>               | Available / complete           | <b>Next maintenance in</b>     |  |
| <b>Last service on / at</b>                      | 03/2024 at 34,748 km           |                                |  |
| <b>Key is / should be</b>                        | 2 / 2                          | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|  |                                | <b>Letter No.</b>              | GN300752   |
| <b>Previous damage / Accident</b>                | None detectable                | <b>Repainting</b>              | None detectable  |
| <b>Inspection conditions</b>                     | sufficient                     | <b>Lifting equipment / pit</b> | yes  |
| <b>Test drive</b>                                | Not performed                  | <b>Engine function test</b>    | Performed  |
| <b>Manufacturer key number/ type code number</b> | 3333 / BNZ 00017               |                                |  |
| <b>Emission standard</b>                         | 2017/1151;WLTP;reine Elektrofz | <b>fine dust sticker</b>       |  |
| <b>Permitted total weight</b>                    | 1,514 kg                       | <b>Empty weight</b>            |  |

## Tyres

### Mounted tyres

| #  | Tyre size      | Type of tyre                                   | Manufacturer | Tread depth |
|----|----------------|--|--------------|-------------|
| 1) | 165/65 R15 81T | All-season tyres on Steel rim with wheel cover | Kleber       | 5mm / 5mm   |
| 2) | 185/60 R15 84T | All-season tyres on Steel rim with wheel cover | Kleber       | 5mm / 5mm   |

### Replacement

| Typ     | Tyre size | Type of tyre            | Manufacturer | Tread depth |
|---------|-----------|-------------------------|--------------|-------------|
| Tirefit |           | Expiration date 02/2028 |              |             |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**



## Equipment

### Equipment

- All-season tyres

### Standard equipment

- |   |  |
|---|--|
| <ul style="list-style-type: none"> <li>• Airbag: Airbag for driver and front passenger</li> <li>• Alarm system pre-installation</li> <li>• Anti-lock braking system and brake assist</li> <li>• On-board computer</li> <li>• Easy-Link</li> <li>• Wheels: 15" steel with "Vegas" wheel covers, diamond-cut with black finish</li> <li>• Flexicase: Open storage compartment between the front seats including USB port</li> <li>• Speed limiter</li> <li>• Back window, heater</li> <li>• ISOFIX/i-Size child seat attachments on the rear outer seats</li> <li>• Rear headrests (2)</li> <li>• Paint finish: Solid</li> <li>• LED daytime running lights</li> <li>• Height-adjustable steering wheel</li> <li>• Package: Interior Look Package Design "Golf Ball" (White)</li> <li>• Upholstery: Fabric "Eclipse" in black with white accents</li> <li>• Tire pressure monitoring system (TPMS)</li> <li>• Electric power steering</li> <li>• Seats: Split-folding rear seat backrest</li> <li>• Striping without</li> <li>• Electronic immobilizer</li> </ul> | <ul style="list-style-type: none"> <li>• Airbag: Side airbags with head and thorax protection at the front</li> <li>• Exterior mirror housings painted in body color</li> <li>• Third brake light</li> <li>• Electronic Stability Program (ESP) with Traction Control (ASR)</li> <li>• electric front windows</li> <li>• Flexicases: Closed glove compartment</li> <li>• ZE Voice sound simulator, speed-dependent</li> <li>• Transmission: Automatic reduction gearbox</li> <li>• rear window wiper</li> <li>• Air conditioning</li> <li>• Automatic air conditioning</li> <li>• Front headrests (2)</li> <li>• Charging cable: Type 2/Type 2 (Mode 3) charging cable with a length of 5.6 m</li> <li>• Light and rain sensor</li> <li>• Package: R &amp; GO Climate Package</li> <li>• Tires: Mobility Kit</li> <li>• Side protection strips in black</li> <li>• Seats: Driver's seat height adjustable</li> <li>• Start-stop system</li> <li>• Door handles and rear spoiler painted in car color</li> <li>• Central locking with radio remote control</li> </ul> |
|---|--|

## Brief expert findings

|                      |  |
|----------------------|--|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.    |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle.                     |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.  |
| Engine function test | An engine test run was performed.  |

## Value reducing factors

| No. | Component group  | Description                                    |
|-----|------------------|--|
| 1   | Sill - left side | Sill - Scratch(es) - Smart repair              |
| 2   | Gearbox          | Gear knob - Damaged - Replace                  |
| 3   | Body             | Body - Glued / labelled - De-glue / neutralise |
| 4   | Misc.            | Inspection / maintenance - Due - Perform       |



## Wear and tear

| No. | Component group | Description   |
|-----|-----------------|---|
| 1   | Vehicle glazing | Windscreen - Stone chips - No deduction                   |
| 2   | Wheel / tyres   | Wheel cover - rear right side - Scratched - No deduction  |
| 3   | Wheel / tyres   | Wheel cover - front right side - Scratched - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
*(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
*(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Navigation




Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Damage 1: Sill - left side: Sill - Scratch(es) - Smart repair



**Damage 1:** Sill - left side: Sill - Scratch(es) - Smart repair



**Damage 2:** Gearbox: Gear knob - Damaged - Replace



**Damage 2:** Gearbox: Gear knob - Damaged - Replace



**Damage 3:** Body: Body - Glued / labelled - De-glug / neutralise



**Damage 3:** Body: Body - Glued / labelled - De-glug / neutralise



**Damage 3:** Body: Body - Glued / labelled - De-glug / neutralise



**Damage 3:** Body: Body - Glued / labelled - De-glue / neutralise



**Damage 4:** Misc.: Inspection / maintenance - Due - Perform



**Damage 4:** Misc.: Inspection / maintenance - Due - Perform



**Wear and tear 1:** Vehicle glazing: Windscreen - Stone chips - No deduction



**Wear and tear 1:** Vehicle glazing: Windscreen - Stone chips - No deduction