



PEUGEOT 2008: GA-420-QN

Vinnumber:	VR3UDYHSMJ724782	Versionname:	PEUGEOT 2008 BLUEHDI 110 S&S ALLURE VP [5P] bvm 6-110CH-6cv (SUV)
First Registrationdate:	8/07/2021	Fiscalpower:	
Expertise Mileage:	122222	Power Kw:	81
Bodytype:	SUV	Body colour:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Headlights Xenon/LED/Laser	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Seat cover lining	Lining Other
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

	215/60/17/96 H			
Summer tyres:	Fr.L.	Goodyear: 55%	Fr.R.	Goodyear: 60%
	Re.L.	Continental: 65%	Re.R.	Continental: 85%
Tyre profile depth FL				4.7
Tyre profile depth FR				4.4
Tyre profile depth RL				3.9
Tyre profile depth RR				2.6
Tyre size FL				215/60 R 17 96 H
Tyre size FR				215/60 R 17 96 H
Tyre size RL				215/60 R 17 96 H
Tyre size RR				215/60 R 17 96 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	-----	------	-----

Interior, Stain, Cleaning





Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RL bitone/polychrome, Scratch(es), Acceptable



Tyre RL, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door FL, Scratch(es), Paint



Door RL, Scratch(es), Polish



Bumper F, Scratch(es), Paint



Bumper moulding F, Scratch(es), Acceptable



Bumper moulding F, Scratch(es), Replace



Door RR, Dent(s) and scratch(es), Acceptable



Wing trim FR, Scratch(es), Replace



Outer door handle FR, Scratch(es), Polish



Door FR, Scratch(es), Polish



Tailgate / Boot, Scratch(es), Polish



Bumper moulding R, Scratch(es), Paint



Bumper moulding R, Deformed / Strained, Replace



Bumper R, Deformed / Strained, Repair and paint (complete)



Bumper corner RR, Scratch(es), Paint



Historique Maintenance

Immatriculation: GA-420-QN Date de 1ère immatriculation: 08/07/2021

Modèle: Peugeot 2008 BLUEHDI 110 S&S ALLURE VP [5P] bvm 6-110CH-6cv (SUV)

Date	Kilométrage	Fournisseur	Descriptif
07/04/2026	117.894	GARAGE OUSTRIC	REVISION
	0		RECYCLAGE
	0		DIVERS CLIM
	0		REVISION
	0		FILTRE A AIR RPLT
	0		FILTRE CLIM RPLT
12/11/2025	109.794	DEMEULE MOBILITE & SERVICES	DIAG
	0		TURBO RPLT
23/07/2025	102.939	GARAGE OUSTRIC	RECYCLAGE
	0		COURROIE DISTRIBUTION RPLT
22/05/2025	100.396	GARAGE OUSTRIC	RECYCLAGE
	0		ARBRE A CAMES RPLT
22/04/2025	98.015	GARAGE OUSTRIC	DIVERS CLIM
	0		REVISION
	0		FILTRE CLIM RPLT
	0		DIVERS ELEC
	0		BALAI ESSUIE GLACE AV
	0		RECYCLAGE
01/04/2025	97.202	GARAGE OUSTRIC	DISQUES PLAQUETTES AV RPLT
	0		ADBLUE
13/03/2025	95.510	FLEET SOLUTIONS FRANCE	REPLACEMENT PNEUS ETE
05/08/2024	75.524	FLEET SOLUTIONS FRANCE	REPLACEMENT PNEUS ETE
02/07/2024	73.452	GARAGE OUSTRIC	REVISION
	0		FILTRE A AIR RPLT
	0		RECYCLAGE
	0		REVISION
	0		FILTRE CLIM RPLT
05/10/2023	51.417	NORAUTO SAS (PRODUIT SPE)	REPLACEMENT PNEUS ETE
05/09/2023	47.164	GARAGE OUSTRIC	REVISION
	0		RECYCLAGE
	0		BALAI ESSUIE GLACE AV
	0		LIQUIDE DE FREIN

Historique Maintenance

Immatriculation: **GA-420-QN**

Date de 1ère immatriculation: **08/07/2021**

Modèle: **Peugeot 2008 BLUEHDI 110 S&S ALLURE VP [5P] bvm 6-110CH-6cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
	0		FILTRE CLIM RPLT
30/08/2022	22.293	GARAGE OUSTRIC	REVISION
	0		FILTRE CLIM RPLT
	0		RECYCLAGE