



BMW 116: 2HLK951

Vinnumber:	WBA31GE0X07T68184	Versionname:	
First Registrationdate:	22/08/2025	Fiscalpower:	
Expertise Mileage:	19069	Power Kw:	
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Petrol		
Maintenance	NOT OK		
Maintenance	min 800 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	Yes		

Options

Number of keys total	1	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/45/18/95 Y			
Summer tyres:	Fr.L.	Nexen: 5 mm	Fr.R.	Nexen: 5 mm
	Re.L.	Nexen: 5 mm	Re.R.	Nexen: 4 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				4.0
Tyre size FL				225/45 R 18 95 Y
Tyre size FR				225/55 R 18 95 Y
Tyre size RL				225/45 R 18 95 Y
Tyre size RR				225/45 R 18 95 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				1957072
Tyre make FR				1957072
Tyre make RL				1957072
Tyre make RR				1957072

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Execute



Ignition key, Missing, Replace



Bumper F, Scratch(es), Spot repair



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Spot repair



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Tyre RR, Tear, Replace



Door FR, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Tyre FR, Tear, Replace



Bodywork, Paint measurement, Acceptable

