



CITROËN BERLINGO: FS-590-YB

Vinnumber:	VR7EFYHYCLJ756946	Versionname:	CITROËN BERLINGO M 1000kg BlueHDi 100 S&S BVM Driver VU [4P] bvm 5-100CH-5cv (fourgonnettesimple cabine)
First Registrationdate:	24/09/2020	Fiscalpower:	
Expertise Mileage:	52980	Power Kw:	75
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	4		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total:	1	Radio:	
Number keys remote:	1	Central consol F:	
GPS big screen color:		Front parking sensors:	
GPS storage:		Rear parking sensors:	
GPS storage:	HD	Sliding door right-side:	
Windows electric F:		Seat cover lining:	Lining Other
Cruise Control:			
Type of climate control:	Manual climate control		

Tyres

205/60/16/96 H				
Summer tyres:	Fr.L.	Hankook: 35%	Fr.R.	Hankook: 20%
	Re.L.	Hankook: 25%	Re.R.	Hankook: 25%
Tyre profile depth FL				6.0
Tyre profile depth FR				7.0
Tyre profile depth RL				6.5
Tyre profile depth RR				6.5
Tyre size FL				205/60 R 16 96 H
Tyre size FR				205/60 R 16 96 H
Tyre size RL				205/60 R 16 96 H
Tyre size RR				205/60 R 16 96 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
--------------	------------	-------	------------

Seat cover FL, Stain, Cleaning



Seat cover FR, Stain, Cleaning



Remote ignition key, Missing, Repair/replace (lump sum)



Door FL, Dent(s) and scratch(es), Acceptable



Door RL, Dent(s), Acceptable



Door trim FL, Scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Acceptable



Bumper F, Scratch(es), Dismount/Mount



Door FR, Dent(s) and scratch(es), Repair and paint (complete)





Roof pillar R, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Acceptable



Side wall RR, Scratch(es), Polish



Bumper R, Scratch(es), Acceptable



Bumper corner RR, Broken, Repair and paint (complete)



Bumper corner RL, Scratch(es), Acceptable



Bodywork, Not original part, Remove lettering



Historique Maintenance

Immatriculation: **FS-590-YB**

Date de 1ère immatriculation: **24/09/2020**

Modèle: **Citroen BERLINGO M 1000kg BlueHDi 100 S&S BVM Driver VU [4P] bvm 5-100CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
23/05/2025	51.917	STELLANTIS &YOU FRANCE SAS	LIQUIDE DE FREIN
	0		FILTRE CLIM RPLT
	0		REVISION
	0		RECYCLAGE
	0		DISQUES PLAQUETTES AV RPLT
	0		BALAISSUIE GLACE AV
	0		DIVERS CLIM
	0		REVISION
	0		FILTRE A AIR RPLT
05/12/2024	49.289	DEKRA AUTOMOTIVE S.A	CONTRE VISITE CT
24/10/2024	48.728	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
17/07/2024	48.163	STELLANTIS &YOU FRANCE SAS	POT CATALYTIQUE FAP RPLT
01/02/2024	47.152	NOMBLLOT AUTOMOBILES	RECYCLAGE
	0		INJECTEUR ADBLUE RPLT
24/05/2023	31.903	STELLANTIS &YOU FRANCE SAS	BALAISSUIE GLACE AV
	0		REVISION
	0		FILTRE A AIR RPLT
	0		REVISION
	0		FILTRE CLIM RPLT
	0		RECYCLAGE
	0		PLAQUETTES AV RPLT