


VOLKSWAGEN PASSAT VARIANT:

Vinnumber:	WVWZZZ3CZKE124942	Versionname:	2.0 TDI SCR 110kW Highline Business
First Registrationdate:	14/06/2019	Fiscalpower:	
Expertise Mileage:	116420	Power Kw:	110
Bodytype:		Body colour	Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3624
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	Tow bar collapsible
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection
Tyres

215/55/17/88 W				
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/55 R 17 88 W
Tyre size FR				215/55 R 17 88 W
Tyre size RL				215/55 R 17 88 W
Tyre size RR				215/55 R 17 88 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


Total cost ex VAT	4728,64
Interior, Damaged, Acceptable	0,00



Air vent R, Broken, Replace	100,15
-----------------------------	--------



Step L, Dent(s) and scratch(es), Spot repair	148,33
--	--------




Wing RL, Dent(s) and scratch(es), Replace and paint	2402,55
---	---------



Bumper R, Deformed / Strained, Replace and paint	1200,24
--	---------



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)	431,58
---	--------



Door FR, Dent(s), Repair and paint (complete)	445,79
---	--------



Bodywork, Accident, Check	0,00
---------------------------	------

