



VOLVO XC40: GL-425-LX

Vinnumber:	YV1XZBWV8P2026468	Versionname:	VOLVO XC40 Recharge T4 211 DCT7 Start VP [5P] bva 7-211CH-7cv (SUV)
First Registrationdate:	2/01/2023	Fiscalpower:	
Expertise Mileage:	178232	Power Kw:	155
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Grey
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Seats electric F L	
GPS big screen color		Seats electric F R	
GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	Lining Other
Type of climate control	Autom climate control		

Tyres

	235/55/18/104 H			
Winter tyres:	Fr.L.	Goodyear: 40%	Fr.R.	Goodyear: 45%
	Re.L.	Goodyear: 15%	Re.R.	Goodyear: 20%
Tyre profile depth FL				5.5
Tyre profile depth FR				5.4
Tyre profile depth RL				7.2
Tyre profile depth RR				7.0
Tyre size FL				235/55 R 18 104 H
Tyre size FR				235/55 R 18 104 H
Tyre size RL				235/55 R 18 104 H
Tyre size RR				235/55 R 18 104 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Seat cover FR, Stain, Cleaning




Tyre FR, Out of tolerance, Replace



Tyre FL, Out of tolerance, Replace



Tyres, Out of tolerance, Replace



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RR bitone/polychrome, Scratch(es), Acceptable



Alloy rim RL bitone/polychrome, Scratch(es), Acceptable





Door RL, Dent(s) and scratch(es), Acceptable



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Paint



Door trim RR, Scratch(es), Replace



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Paint



Bumper spoiler Rear, Unclassped, Dismount/Mount



Bumper moulding R, Scratch(es), Replace



Historique Maintenance

Immatriculation: GL-425-LX Date de 1ère immatriculation: 02/01/2023

Modèle: Volvo XC40 Recharge T4 211 DCT7 Start VP [5P] bva 7-211CH-7cv (SUV)

Date	Kilométrage	Fournisseur	Descriptif
05/01/2026	154.264	FELIX FAURE AUTOMOBILES*	PLAQUETTES AR RPLT
	0		BALAI ESSUIE GLACE AR
	0		RECYCLAGE
	0		REVISION
	0		PLAQUETTES AV RPLT
	0		BALAI ESSUIE GLACE AV
14/10/2025	140.940	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS HIVER
26/05/2025	120.306	FELIX FAURE AUTOMOBILES*	LIQUIDE DE FREIN
	0		REVISION ET CLIM ET AIR ET BOUGIES
	0		RECYCLAGE
24/10/2024	90.473	FELIX FAURE AUTOMOBILES*	RECYCLAGE
	0		REVISION ET CLIM
23/05/2024	67.124	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS 4 SAISONS
03/04/2024	61.465	FELIX FAURE AUTOMOBILES*	HUILE BV RPLT
	0		REVISION ET CLIM ET AIR ET BOUGIES
	0		BALAI ESSUIE GLACE AV
	0		RECYCLAGE
	0		BALAI ESSUIE GLACE AR
18/09/2023	31.752	FELIX FAURE AUTOMOBILES*	REVISION ET CLIM
	0		RECYCLAGE