MACADAM ITALY S.R.L.

Piazza Belgioioso, 2 - 20121 Milano (MI)

Tel. - Fax

Piva: 12729790969

Report No.	Expert's report for	Type of insurance
	Alphabet Italia	Perizia

Policyholder	Opposite party	Opposite party company

Operation	Claim number	Code / Agency	Date accident
2026			16/10/2026

Expert code	Adjuster code	Policy number	Injured person can recover the VAT

Date assignment	Date first survey	Place	C/O	Repairs	Photo	Lien in favor of	Expiry date
16/10/2026	28/10/2026	VIMODRONE					

Ownership certificate: Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN) — Formerly plate:

Lessee / Co-owner — Date of overhaul:


Vehicle (Brand - Model - Version)	Plate	Vin Chassis	First Registration
FORD TRANSIT COURIER 1.5 TDCi 75 cv Trend	GM710VP	WF0WXXTACWNG85698	09/02/2023

Usage status	Km	Tyres %	Color	Type of enamel	Consistency of damage	Type of Expert's report
NON CONOSCIUTO	77300	40	BIANCO	PASTEL/DOUBLE		NOT DEFINITIVE

Equipment

Approval code	For commercial vehicles	Carrying Qls	Tare,Q	Wheelbase	Seats No.	Axles
		0	0		0	0

Commercial value (C)	Wrecked car value	Value by difference	Ancillary expenses



	Damaged items / restoration operations		SR Dif	SR Time	LA Dif	LA Time	VE Dif	VE Time	ME Time	D.M. S.C.	Costs of spare parts * (VAT excluded)
1 2344349	Internal panel of lower rear hinged door	L	S		S		S				
1 1865321	Rear floor mat		S		S		S				
1 1746251	Front wheel cap	L	S		S		S				
1 1746251	Front wheel cap	R	S		S		S				
1 1746251	Rear wheel cap	L	S		S		S				
1 1746251	Rear wheel cap	R	S		S		S				
1 Codice Ricambio	Pneum. post.	L	S		S		S				
1 1919717	Series cylinder locks		S		S		S				
1 2269528	External rear-view mirror cap	R	S		S		S				
1 1865569	Rear bumper		S		S		S				
1 1929295	Dashboard lower side glove compartment		S		S		S				
1 2261626	Front bumper		M		M		G				
1 2782156	Front bonnet		M		M		G				
1 1857499	Roof		M		M		M				
1 2484902	Rear door	R	M		M		M				
1 2292146	Rear hinged loading door	L	M		M		M				
1 2418507	Compartment structure of door with rear mudguard	L	L		M		M				
1 1850392	Rear mudguard upper part	R	L		G		G				
1 1850311	Rear mudguard lower part	R	L		L		M				
1 Codice Ricambio	Rimozione adesivo post.	R									
1 Codice Ricambio	Smacchiatura interni										
1 Codice Ricambio	Chiave mancante										
1 Codice Ricambio	Cruscotto abitacolo PRM										
1 Codice Ricambio	Volante - PRM										

New for old value (N)

Remarks

PNEUM: LASSA ESTIVE ANT. 4mm POST. DX LASSA 5mm E POST. SX CONTINENTAL ESTIVE 4mm DA SOST. PER MARCA DIVERSA 195/60 R15 88H.
VHL SPORCO, GRANDINATO.
COMPUTO CORRELATO ALL UTILIZZO DEL MEZZO.

Prepared by A.M.G. Software di Torino - Ph. (011) 599.870 - Fax (011) 595.323 - www.amgsoftware.it - e-mail info@amgsoftware.it