



Opel Corsa: N801RX

Vinnumber:	VXKUHZKXZM4316422	Versionname:	Corsa-E 3 fase lader 100kW / 50kWh Edition
First Registrationdate:	21/12/2021	Fiscalpower:	
Expertise Mileage:	73571	Power Kw:	100
Bodytype:		Body colour	White Jade
Gearbox:	Automatic	Paint type	Opaque
Transmission:		Type of rims (mounted)	Steel
Fueltype:	Electric	Parking lot	327
Number of seats	5		
Type of rims (mounted)	Steel		
Maintenance needed	No		

Options

Number of keys total	2
Autom climate control	
Radio multimedia	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 55 / 16 / 87 / H / Steel	7,1 mm	Continental	All season
	Right	195 / 55 / 16 / 87 / H / Steel	6,7 mm	Continental	All season
Rear	Left	195 / 55 / 16 / 87 / H / Steel	7,0 mm	Continental	All season
	Right	195 / 55 / 16 / 87 / H / Steel	7,1 mm	Continental	All season

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Bumper F, Crack, Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace and paint



Kenteken	N801RX
Merk Model	Opel Corsa-E 3 fase lader 100kW / 50kWh Edition
Brandstofsoort	Elektrisch
Datum deel1	21-12-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
22-01-26	65.690	Onderhoudsbeurt
22-01-26	65.690	Tractie batterij lader
22-01-26	65.690	Vervanging band
19-11-25	63.044	APK
19-11-25	63.044	Ruitenwisherblad(en) voorzijde
12-11-24	47.803	Onderhoudsbeurt
27-12-23	26.730	Onderhoudsbeurt
18-09-23	17.726	Vervanging band
09-02-23	5.408	Onderhoudsbeurt