



VOLVO XC90: FV-983-JY

Vinnumber:	YV1LFBMVDM1716297	Versionname:	VOLVO XC90 Recharge T8 AWD GT 8 Inscription Luxe VP [5P] bva 8-390CH-19cv (SUV)
First Registrationdate:	26/11/2020	Fiscalpower:	
Expertise Mileage:	76562	Power Kw:	287
Bodytype:	SUV	Body colour:	Dark Blue
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4 Wheel-drive	Interior colour:	Light Beige
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Tow bar	
Number keys remote	1	Radio	
GPS big screen color		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Central consol F	
Steering wheel leather		Luggage cover	
Seats F heated		Headlights Xenon/LED/Laser	
Type of climate control	Autom climate control	Headlight sprinkler	
		Front parking sensors	
		Rear parking sensors	
		Rear view camera	
		Seat cover lining	Lining Leather

Tyres

	275/45/20/110 Y			
Summer tyres:	Fr.L.	Hankook: 30%	Fr.R.	Hankook: 30%
	Re.L.	Hankook: 30%	Re.R.	Hankook: 35%
Tyre profile depth FL				6.1
Tyre profile depth FR				6.2
Tyre profile depth RL				6.2
Tyre profile depth RR				6.0
Tyre size FL				275/45 ZR 20 110 Y
Tyre size FR				275/45 ZR 20 110 Y
Tyre size RL				275/45 ZR 20 110 Y
Tyre size RR				275/45 ZR 20 110 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)




Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door FL, Dent(s), Repair and paint (complete)



Wing trim FL, Scratch(es), Paint



Bumper F, Scratch(es), Paint



Charging cable (normal), Missing, Replace



Bumper R, Scratch(es), Paint



Bumper spoiler Rear, Scratch(es), Paint



Historique Maintenance

Immatriculation: FV-983-JY Date de 1ère immatriculation: 26/11/2020

Modèle: Volvo XC90 Recharge T8 AWD GT 8 Inscription Luxe VP [5P] bva 8-390CH-19cv (SUV)

Date	Kilométrage	Fournisseur	Descriptif
20/01/2026	74.564	ACTENA AUTOMOBILES	DISQUES PLAQUETTES AR RPLT
	0		REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV AR
	0		LIQUIDE DE FREIN
25/03/2025	70.199	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS ETE
14/01/2025	69.158	CARSUR	CONTROLE TECHNIQUE
04/09/2024	67.426	ACTENA AUTOMOBILES	PLAQUETTES AR RPLT
	0		REVISION ET CLIM
	0		PLAQUETTES AV RPLT
	0		BATTERIE RPLT
07/06/2023	48.646	ACTENA AUTOMOBILES	LIQUIDE DE FREIN
	0		BALAIS ESSUIE GLACE AV AR
	0		REVISION ET CLIM ET AIR ET BOUGIES
27/01/2022	23.382	ACTENA AUTOMOBILES	REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV