



Expertise

Protocol number: 46554109
Order No. / Reference: 26530434
Inspection date: 14 Jul 2026

Manufacturer: Skoda
VIN: TMBJJ7NS5N8051359

Model: Kodiaq 2.0 TDI DSG Tour



Vehicle details	
Manufacturer / Type / Model / Equipment	
Skoda Kodiaq 2.0 TDI DSG Tour	
Vehicle Identification number	TMBJJ7NS5N8051359
Mileage (Read)	87,775 km
First registration	21 Jun 2022
Number of holders	1
Power / Engine displacement	110 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Energy-blau Uni
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black
readiness to drive	Not roadworthy / moveable



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	13,400 km
Last service on / at	02/2026 at 82,572 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ920883
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	8004 / ART 02729		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,350 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/50 R19 99V	Summer tyres on Light alloy	Hankook	3mm / 3mm
2)	235/50 R19 99V	Summer tyres on Light alloy	Hankook	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 99H	Winter tyres on Light alloy	Continental	6mm / 6mm
2)	215/65 R17 99H	Winter tyres on Light alloy	Continental	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 12V socket in the center console and in the trunk
- Storage compartments behind the wheel arches in the trunk
- Airbag, driver and passenger
- Airbag, head airbags
- Allergen filter
- Traction control (ASR)
- Traveller Plus Assistance System (DSG)
- Electrically adjustable and heated exterior mirrors with integrated side indicators
- Hydraulic brake assist (HBA)
- Grey headliner
- Decorative inlay Anodized Cross
- Diesel particulate filter
- Third brake light
- eCall
- Electronic parking brake including auto-hold function
- ESC Electronic Stability Control
- Electric windows front and rear
- Front radar assistant including city emergency braking function with pedestrian detection
- Transmission: 7-speed dual-clutch transmission (DSG)
- Illuminated glove compartment
- Kessy - keyless entry and start-stop system
- Climatronic air conditioning (2-zone)
- Front and rear headrests are height-adjustable.
- LED matrix headlights and dynamic high beam assist (Light Assist)
- Steering wheel: Sport leather steering wheel with multifunction buttons including paddle shifters.
- Front center armrest, including storage compartment
- Engine drag torque control (MSR)
- Multi-collision brake
- Package: Family
- Front and rear parking sensors
- Wheel arch cover
- Radio accessories: 8 speakers
- Radio accessories: SmartLink
- Tire pressure monitoring
- Wheels: RunFlat tires with Seal technology
- Rear seat backrest split 60:40, foldable, longitudinally adjustable, backrest angle adjustable
- Electromechanical power steering
- Seats: Heated front and outer rear seats
- Seats: Height-adjustable front seats
- Sun visor on driver and passenger side with illuminated vanity mirror
- Telephone: Convenient hands-free telephone system including phone box
- Lashing eyes in the trunk
- Central locking with remote control
- Storage compartment on the left wheel arch
- Option to opt out of standard extended warranty
- front aero windshield wipers
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Anti-lock braking system (ABS)
- Dashboard in black / black, door trim in black
- Electrically folding exterior mirrors including interior and driver's side mirrors with automatic dimming
- Hill start assist
- Care Connect: Proactive services (10-year term)
- Roof rails, black
- Anti-theft alarm system
- Tachometer
- Easy Start (start-stop button)
- Electric tailgate operation including comfort opening
- Electronic transverse differential lock (XDS+)
- Driving light assistant and rain sensor
- High Beam Assist (Light Assist)
- front and rear floor mats
- Closed storage compartment on the driver's side
- Tinted windows
- Isofix anchorage on the outer rear seats including top tether
- Boot cover, roll-up and removable
- Paint finish: Solid
- LED taillights in crystal glass look & LED license plate lights
- Reading lights at the front of the headliner
- Rear center armrest with cup holders and pass-through option
- Multifunction display in the instrument cluster, color
- Fog lights with integrated LED daytime running lights
- Parking assist
- Upholstery: Cloth
- Radio: Amundsen infotainment system (tour)
- Radio accessories: Digital radio reception DAB+
- Radio accessories: Wireless SmartLink
- Wheels: 19" Procyon Aero alloy wheels, grey, diamond-cut finish
- Heated windshield washer nozzles, front
- Headlights washer / wiper system
- Kodiahq seat belts
- Seats: Adjustable lumbar support in the front seats
- Skoda Care Connect
- Sunshade roller blind for the rear side windows
- Sunset
- Front door sill trims
- Variable fastening concept in the trunk
- Immobiliser



Extra equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> Swiveling trailer hitch (with electric release, including trailer stabilization) | <ul style="list-style-type: none"> Rear view camera Windscreen, wirelessly heated |
|--|---|

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Bonnet	Insulation lining - Damage caused by marten / rodent - Replace
3	Front bumper	Front bumper - Scratched - Smart repair
4	Boot lid / rear door	Boot lid - Scratched - Smart repair
5	Mudguard - left side	Mudguard - left side (schleifen + polieren) - Scratched - Smart repair
6	Door - front left side	Door (schleifen + polieren) - Scratched - Smart repair
7	Wheel / tyres	Tyre - rear right side - Damaged - Replace
8	Wheel / tyres	Tyre - front right side - Damaged - Replace
9	Wheel / tyres	Alloy rim - rear right side - Scratched - Loss in value
10	Front bumper	Spoiler - Scratched - Replace
11	Rear bumper	Spoiler - Scratched - Replace
12	Side panel - rear left side	Side panel - Dent / paintcoat damage - Repair and paint
13	Rear bumper	Rear bumper - Scratched - Paint
14	Bonnet	Bonnet - Scratched - Paint
15	Vehicle glazing	Windscreen - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Body	A-pillar - right side - Scratch(es) - No deduction
2	Door - rear left side	Door - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.

Der beiliegende Radsatz ist nicht Bestandteil der vorliegenden Fahrzeugausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Bonnet: Insulation lining - Damage caused by marten / rodent - Replace



Damage 2: Bonnet: Insulation lining - Damage caused by marten / rodent - Replace




Damage 3: Front bumper: Front bumper - Scratched - Smart repair



Damage 3: Front bumper: Front bumper - Scratched - Smart repair



Damage 4: Boot lid / rear door: Boot lid - Scratched - Smart repair



Damage 4: Boot lid / rear door: Boot lid - Scratched - Smart repair



Damage 4: Boot lid / rear door: Boot lid - Scratched - Smart repair




Damage 4: Boot lid / rear door: Boot lid - Scratched - Smart repair



Damage 5: Mudguard - left side: Mudguard - left side (schleifen + polieren) - Scratched - Smart repair



Damage 5: Mudguard - left side: Mudguard - left side (schleifen + polieren) - Scratched - Smart repair




Damage 6: Door - front left side: Door (schleifen + polieren) - Scratched - Smart repair



Damage 6: Door - front left side: Door (schleifen + polieren) - Scratched - Smart repair



Damage 7: Wheel / tyres: Tyre - rear right side - Damaged - Replace



Damage 7: Wheel / tyres: Tyre - rear right side - Damaged - Replace



Damage 8: Wheel / tyres: Tyre - front right side - Damaged - Replace



Damage 8: Wheel / tyres: Tyre - front right side - Damaged - Replace



Damage 9: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



Damage 9: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



Damage 10: Front bumper: Spoiler - Scratched - Replace



Damage 10: Front bumper: Spoiler - Scratched - Replace



Damage 10: Front bumper: Spoiler - Scratched - Replace




Damage 11: Rear bumper: Spoiler - Scratched - Replace




Damage 11: Rear bumper: Spoiler - Scratched - Replace




Damage 12: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 12: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 12: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 13: Rear bumper: Rear bumper - Scratched - Paint



Damage 13: Rear bumper: Rear bumper - Scratched - Paint



Damage 13: Rear bumper: Rear bumper - Scratched - Paint



Damage 13: Rear bumper: Rear bumper - Scratched - Paint




Damage 13: Rear bumper: Rear bumper - Scratched - Paint



Damage 14: Bonnet: Bonnet - Scratched - Paint




Damage 14: Bonnet: Bonnet - Scratched - Paint




Damage 14: Bonnet: Bonnet - Scratched - Paint



Damage 14: Bonnet: Bonnet - Scratched - Paint



Damage 15: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 15: Vehicle glazing: Windscreen - Broken / torn - Replace



Wear and tear 1: Body: A-pillar - right side - Scratch(es) - No deduction



Wear and tear 1: Body: A-pillar - right side - Scratch(es) - No deduction



Wear and tear 2: Door - rear left side: Door - Scratch(es) - No deduction



Wear and tear 2: Door - rear left side: Door - Scratch(es) - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: TMBJJ7NS5N8051359
Hersteller / Modell: SKODA SKODA Kodiaq 2.0 TDI DSG Tour

Datum	KM-Stand	Beschreibung
24.02.2026	82.572	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben hinten; Bremsscheiben vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
09.12.2025	77.906	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
13.06.2025	66.082	AU
05.11.2024	52.911	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
25.09.2023	27.543	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges