MACADAM









BMW X1: FG-677-EF

Vinnumber:	**WBAJH510305N13820**	Versionname:	**BMW X1 sDrive18d xLine BVA8 VP [5P] bva 8-150CH-8cv (SUV)**
First Registrationdate:	**16/05/2019**	Fiscalpower:	
Expertise Mileage:	**145862**	Power Kw:	**110**
Bodytype:	**SUV**	Body colour	**Grey**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Dark Grey**
Fueltype:	**Diesel**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		
Last service correctly filled in	**No**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Seats electric F L	
GPS big screen color		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Headlights Xenon/LED/Laser	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Steering wheel leather		Rear view camera	
Seats F heated		Seat cover lining	**Lining Other** **Lining Leather**
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**225/50/18/99 W**			
	Fr.L.	**Hankook: 50%**	Fr.R.	**Hankook: 50%**
	Re.L.	**Hankook: 35%**	Re.R.	**Hankook: 35%**

Tyre profile depth FL	**4.9**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**6.0**
Tyre profile depth RR	**5.8**
Tyre size FL	**225/50 R 18 99 W**
Tyre size FR	**225/50 R 18 99 W**
Tyre size RL	**225/50 R 18 99 W**
Tyre size RR	**225/50 R 18 99 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**260**
Tyre make FR	**260**
Tyre make RL	**260**
Tyre make RR	**260**

Assistance equipment

Interior, Stain, Cleaning





Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)





Tyre FL, Tear, Replace





Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)






Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)





Reflector, Broken, Replace




Bumper spoiler Rear, Scratch(es), Repair and paint (complete)




Bodywork, Paint measurement, Acceptable



ALPHABET

Historique Maintenance

Immatriculation: **FG-677-EF** Date de 1ère immatriculation: **16/05/2019**

Modèle: **BMW X1 sDrive18d xLine BVA8 VP [5P] bva 8-150CH-8cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
25/02/2025	136.208	NEUBAUER DISTRIBUTEUR CHAMBOURCY	DIAG
	0		LIQUIDE DE FREIN
27/12/2024	136.097	NEUBAUER DISTRIBUTEUR CHAMBOURCY	DIVERS
	0		ESSAI
	0		TELECHARGEMENT CALCULATEUR
14/02/2023	83.455	NEUBAUER DISTRIBUTEUR CHAMBOURCY	PLAQUETTES AV RPLT
	0		LIQUIDE DE FREIN
	0		ADBLUE
	0		REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV AR
	0		PLAQUETTES AR RPLT
04/11/2021	52.292	NEUBAUER DISTRIBUTEUR CHAMBOURCY	SERVICE CONTROLE VH BMW MINI
	0		DISQUES PLAQUETTES AV RPLT
	0		REVISION ET CLIM ET AIR ET CARBURANT
23/08/2021	43.075	NEUBAUER DISTRIBUTEUR CHAMBOURCY	FERMETURE DOSSIER TECHNIQUE
	0		BV COMPLETE RPLT
	0		TELECHARGEMENT CALCULATEUR
	0		DIAG
	0		ESSAI
29/10/2020	26.239	NEUBAUER DISTRIBUTEUR CHAMBOURCY	PLAQUETTES AR RPLT
	0		ADBLUE
	0		BALAIS ESSUIE GLACE AV AR
	0		REVISION ET CLIM
	0		PLAQUETTES AV RPLT