MACADAM









DS 7 CROSSBACK: GC-763-PN

Vinnumber:	**VR1JCYHZUMY532537**	Versionname:	**DS DS 7 CROSSBACK BlueHDi 130 Automatique BASTILLE + VP [5P] bva 8-130CH-7cv (SUV)**
First Registrationdate:	**25/10/2021**	Fiscalpower:	
Expertise Mileage:	**64763**	Power Kw:	**96**
Bodytype:	**SUV**	Body colour	**Black**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Seats electric F L	
GPS big screen color		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Headlights Xenon/LED/Laser	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Steering wheel leather		Rear view camera	
Type of climate control	**Autom climate control**	Seat cover lining	**Lining Other**

Tyres

Summer tyres:	**235/50/19/103 V**			
	Fr.L.	**Continental: 70%**	Fr.R.	**Continental: 70%**
	Re.L.	**Continental: 60%**	Re.R.	**Continental: 80%**

Tyre profile depth FL	**3.8**
Tyre profile depth FR	**3.6**
Tyre profile depth RL	**4.3**
Tyre profile depth RR	**2.9**
Tyre size FL	**235/50 R 19 103 V**
Tyre size FR	**235/50 R 19 103 V**
Tyre size RL	**235/50 R 19 103 V**
Tyre size RR	**235/50 R 19 103 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Tyre FL, Out of tolerance, Replace




Tyre RR, Out of tolerance, Replace




Tyre FR, Out of tolerance, Replace




Alloy rim FR bitone/polychrome, Scratch(es), Acceptable






Wing RL, Scratch(es), Paint




Bumper F, Scratch(es), Paint




Door trim FR, Scratch(es), Replace




Door FR, Scratch(es), Paint




Door RR, Dent(s), Repair and paint (complete)




Rubber seal for boot lid, Tear, Replace




Bumper R, Scratch(es), Paint




ALPHABET

Historique Maintenance

Immatriculation: **GC-763-PN** Date de 1ère immatriculation: **25/10/2021**

Modèle: **DS 7 CROSSBACK BlueHDi 130 Automatique BASTILLE + VP [5P] bva 8-130CH-7cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
09/07/2026	55.613	STELLANTIS &YOU MARSEILLE MICHELET II	PLAQUETTES AR RPLT
			FILTRE CLIM RPLT
			LIQUIDE DE FREIN
			FILTRE A AIR RPLT
			FILTRE A CARBURANT RPLT
			CONTROLE PH LIQUIDE REFROIDISSEMENT
			BALAI ESSUIE GLACE AR
			BALAIS ESSUIE GLACE AV
			ADBLUE
			REVISION
08/03/2024	36.149	STELLANTIS &YOU FRANCE SAS	FILTRE CLIM RPLT
			LIQUIDE DE FREIN
			RECYCLAGE
			REVISION
16/12/2022	33.291	STELLANTIS &YOU FRANCE SAS	REVISION
			ADBLUE
			RECYCLAGE
			BALAIS ESSUIE GLACE AV