MACADAM









CITROEN C3: 2ENP119

Vinnumber:	**VF7SXHMRVNT577978**	Versionname:	
First Registrationdate:	**12/12/2022**	Fiscalpower:	
Expertise Mileage:	**22435**	Power Kw:	
Bodytype:		Body colour	**Grey**
Gearbox:	**MAN 5 VIT**	Type of rims (mounted)	**Aluminium**
Transmission:	**Front**		
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**19980.0**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		
Registration Certificate Home (BE)	**No**		

Options

Number of keys total	**2**	Luggage cover	
Number keys remote	**2**	Rear parking sensors	
Windows electric F			
Windows electric R			
Board Computer			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	**Headlighting LED**		
Type of GPS	**No GPS**		
Type of Lining	**Lining fabrics**		
Type of climate control	**Autom climate control**		
Type of GPS storage	**N.A.**		

Tyres

Summer tyres:	**205/55/16/94 V**			
	Fr.L.	**Michelin: 5 mm**	Fr.R.	**Michelin: 5 mm**
	Re.L.	**Michelin: 5 mm**	Re.R.	**Michelin: 5 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**205/55 R 16 94 V**
Tyre size FR	**205/55 R 16 94 V**
Tyre size RL	**205/55 R 16 94 V**
Tyre size RR	**205/55 R 16 94 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Total cost ex VAT	**530,09**
Interior, Dirty, Cleaning	**32,07**






Headrest RR, Missing, Replace	66,00



Dashboard, Scratch(es), Smart repair	121,70



Bumper moulding F, Scratch(es), Acceptable	0,00



Door FL, Scratch(es), Acceptable	0,00



Door FL, Repaired, Check	0,00



Door RL, Dent(s) and scratch(es), Spot repair	127,11



Wing trim RL, Scratch(es), Acceptable	0,00



Wing RL, Scratch(es), Acceptable	0,00




Boot cover, Scratch(es), Acceptable	0,00






Boot lid covering R, Scratch(es), Acceptable	0,00




Bumper trim R, Scratch(es), Acceptable	0,00






Bumper R, Scratch(es), Spot repair	183,21











Bumper moulding R, Scratch(es), Acceptable	0,00




Outer door handle FR, Scratch(es), Acceptable	0,00