



PEUGEOT Expert: 1226-MLV

Vinnumber:	VF3VBYHVMP7867113	Versionname:	Furgón BlueHDi 120 S&S 6v Standard furgón 88kW 4P manual
First Registrationdate:	28/11/2023	Fiscalpower:	
Expertise Mileage:	194748	Power Kw:	
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	No		

Options

Number of keys total:	2	Radio:	
Number keys remote:	2	Rear parking sensors:	
Windows electric F:			
Cruise Control:			
Type of climate control:	Manual climate control		


Tyres

215/65/16/104 T				
Summer tyres:	Fr.L.	Dunlop: 3 mm	Fr.R.	Dunlop: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				215/65 R 16 104 T
Tyre size FR				215/65 R 16 104 T
Tyre size RL				215/65 R 16 104 T
Tyre size RR				215/65 R 16 104 T
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				257
Tyre make FR				257
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
--------------	------------	-------	------------


Door panel RL, Scratch(es), Repair/replace (lump sum)



Door panel RR, Scratch(es), Repair/replace (lump sum)




Door panel FL, Scratch(es), Repair/replace (lump sum)



Steering wheel, Worn, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Wing FL, Dent(s), Repair and paint (complete)



Door FL, Scratch(es), Paint



Wing RL, Scratch(es), Paint



Rear light L, Broken, Replace



Bumper F, Scratch(es), Paint



Bumper moulding F, Dent(s), Repair and paint (complete)



Wing RR, Dent(s), Repair and paint (complete)



Sliding door R, Dent(s), Repair and paint (complete)



Outer door handle RR, Broken, Replace



Door FR, Dent(s), Repair and paint (complete)



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Parking sensor R, Missing, Replace



Boot door panel RL, Scratch(es), Paint



Boot door panel RR, Scratch(es), Paint



Tyres, No damage, Check





Bodywork, Accident, Check

