MACADAM








OPEL Crossland: 5285-MSR

Vinnumber:	**W0V7D9ED2R4207388**	Versionname:	**1.2 81kW (110CV) Elegance Pack todoterreno 81kW 5P manual**
First Registrationdate:	**28/06/2024**	Fiscalpower:	
Expertise Mileage:	**63091**	Power Kw:	
Bodytype:	**SUV**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Type of rims (mounted)	**Aluminium**
Transmission:			
Fueltype:	**Petrol**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**No**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**No**		

Options

Number of keys total	**2**	Central consol F	
Number keys remote	**1**	Luggage cover	
GPS big screen color		Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Radio multimedia			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**195/60/16/89 V**			
	Fr.L.	**Goodyear: 6 mm**	Fr.R.	**Goodyear: 6 mm**
	Re.L.	**Bridgestone: 4 mm**	Re.R.	**Bridgestone: 4 mm**

Tyre profile depth FL	**6.0**
Tyre profile depth FR	**6.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**195/60 R 16 89 V**
Tyre size FR	**195/60 R 16 89 V**
Tyre size RL	**195/60 R 16 89 V**
Tyre size RR	**195/60 R 16 89 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**255**
Tyre make RR	**255**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

MOT certificate, Missing, Repair/replace (lump sum)




Registration document, Missing, Repair/replace (lump sum)




Interior, Dirty, Cleaning




Door RL, Scratch(es), Repair and paint (complete)




Door FL, Scratch(es), Repair and paint (complete)





Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)




Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)




Outside rear-view mirror housing R, Scratch(es), Acceptable




Door FR, Scratch(es), Repair and paint (complete)





Door RR, Scratch(es), Repair and paint (complete)




Wing trim RR, Scratch(es), Paint




Bumper R, Scratch(es), Repair and paint (complete)




Tyres, No damage, Check






ALPHABET

Datos del vehículo

Marca	OPEL	Matrícula	5285-MSR
Modelo	Crossland	VIN	W0V7D9ED2R4207388
Versión	1.2 81kW (110CV) Elegance Pack todoterreno 81kW 5P manual		

Histórico

Fecha	Descripción	Kilómetros	Taller
10/03/2025	Revisión 1 año	21619	AUTOMARES S.L.
06/11/2025	Aceite motor - Precio litro pactado, Arandela / tapón cárter, Bujía, Filtro aceite - EQUIVALENTE EN EUROREPAR - Economic, Filtro aire - EQUIVALENTE EN EUROREPAR - Economic, Filtro antipolen - EQUIVALENTE EN EUROREPAR - Economic, Serv inspección 50000 KM, Sustituir Bujía, Tasa de gestión de aceites usados	41262	MOVIL-5 S.L.
03/12/2025	Alineado sencillo, Ecotasa - N2, Goodyear / 578293 195/60X16 GYEAR.EFIG.PERF2 89V, Sustitucion y kit de montaje	43902	TALLERES Y NEUMATICOS CABA S.L.
10/09/2026	Aceite motor - - - ALP EURO, Arandela / tapón cárter - CAUTEX - Rec.Plat. EuroTaller, Bujía, Filtro aceite, Filtro aire, Filtro antipolen - BOSCH - Rec.Plat. EuroTaller, Importe de pago por uso, Serv inspección 50000 KM, Sustituir Bujía, Tasa de gestión de aceites usados	63214	INTERCEPTOR CARS S.L.

Fecha	Descripción	Kilómetros	Taller