



Mercedes GLA-Klasse (UKL): 2CDS776

Vinnumber:	W1N2477101J371326	Versionname:	GLA180d Business Solution 2.0d 116pk/cv 5p 8G-DCT
First Registrationdate:	16/06/2022	Fiscalpower:	
Expertise Mileage:	112695	Power Kw:	85
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	A7 + 174 dagen		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

235/55/18/100 W				
Summer tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				5.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				235/55 R 18 100 W
Tyre size FR				235/55 R 18 100 W
Tyre size RL				235/55 R 18 100 W
Tyre size RR				235/55 R 18 100 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Service, Maintenance, Check



Windscreen, Scratch(es), Replace



Bumper F, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Tailgate / Boot, Dent(s), Paintless dent repair



Kenteken	2CDS776
Merk Model	Mercedes GLA180d Business Solution 2.0d 116pk/cv 5p 8G-DCT
Brandstofsoort	Diesel
Datum deel1	6/16/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
12/11/25	103,243	mercedes assyst b	Uitvoeren
1/18/25	78,108	brandstoffilter	Vervangen
1/18/25	78,108	klein materiaal	
1/18/25	78,108	luchtfilter	Vervangen
1/18/25	78,108	mercedes assyst a	Uitvoeren
1/18/25	78,108	remvloeistof	Vervangen
1/2/24	50,556	batterij	Vervangen
1/2/24	50,556	klein materiaal	Uitvoeren
1/2/24	50,556	mercedes assyst b	Uitvoeren
1/2/24	50,556	ruitenswisserrubber vooraan	Vervangen
4/6/23	25,269	klein materiaal	Uitvoeren
4/6/23	25,269	mercedes assyst a	Uitvoeren
4/6/23	25,269	ruitenswisserrubber vooraan	Vervangen