BMW

VIN: WBA7K310707J11027



Description

Registration number 2AHE116	**First registration date** 01/04/2021	**Odometer** 152746 km
Color BLACK SAPPHIRE METALLIC	**Model year** 2020	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
CO2 151	**Engine displacement** 1499	**Gearbox type** Automatic
Engine type Combustion	**Number of gears** 7	**Drivetrain** Front Wheel Drive (FWD)
Max power 100 KW		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Vehicle Equipments

Standard

vehicle speed limiter	armrest front	Advantage
airbag driver side/passenger side	airbag passenger side deactivatable	sidebag front
generator 120 A	immobilizer	battery 70 Ah
BMW Live cockpit	BMW Live cockpit Professional	start-stop button
body: 5-door	air conditioning	steering column (steering wheel) mechanic. adjustable
dynamic traction control (DTC)	tire pressure control system	radio reception digital (DAB)
electronically locking differential	power steering Servotronic	theft protection for wheels (rim locks)
rear seat backrest split/folding	dynamic stability control (DSC) with extended scope	light and rain sensor
Entretien: Véhicule avec Intervalle de vidange d'huile 30000 Km / 24 mois	gasoline particulate filter (GPF)	refrigerant R 1234 YF
parking brake electromechanical	windshield washer jets heated	Light-alloy rims
window lifter electric front + rear	engine 1,5 liter - 100 kW 12V catalyst	low emissions according to emission standard Euro 6d
trip computer	Equipment package: Connected	Equipment package: ConnectedDrive Services
Storage package	USB connection in rear seat area	lashing eyes cargo space sideways
Parkpilot system front and rear	Pneus 205/55 R16 ..V	trailer stabilization program (TSA)
headlight LED	headlight leveling control	cruise control with brake function
exterior mirror electrically adjustable and heated	Isofix mounts for child seat at rear seat	floor mats velours
head airbag system rear	head airbag system front	antilock braking system (ABS)
driver assistance system: Active Guard plus (lane assist, front-end collission warning)	driver assistance system: Performance Control	driver assistance system: alertness assistant
driver assistance system: driving-experience switch	personalization system (Personal Profile)	Service system: intelligent emergency call incl. TeleServices
Service system: ConnectedDrive Services	start/stop system	warning triangle
Blue & Me (Bluetooth with voice control, USB port, MP3)	Steering AV European market (EU specific)	central locking system
heat protection glazing tinted	daytime running lights LED	

Optional

alarm system	transmission 7-speed - dual-clutch transmission with Steptronic	reversing camera
active hood	interior equipment interior trim strips Illuminated Berlin	roof liner anthracite (BMW Individual)
model variant CO2 scope (code 1CB)	norme de dépollution Euro 6 RDE 2	Parking assistant package
driver assistance system: reversing assistant	metallic paintwork	fuel tank: 105 liter
exterior mirror electrically folding	interior mirror with automatic dimming	seat covers/upholstery: cloth
seat front right mechanical height-adjustable	seat heating front	sports seats front
système de récupération des gaz d'échappement (Blow-by-Heater)	Service system: legally required emergency call feature	steering wheel (sport/leather) with multiple function
veh. without model lettering		

Statement details

Inspection loc
PARC HÖDLMAYR TONGEREN

Statement date
23/10/2026

Inspection approval date
26/10/2026

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Control

Detected issues


Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Personal Data / -	Non Compliant	Carry out
	 		
002	Door housing seal / Back Left	Non Compliant	Refit
	 		
003	Rear windscreen / Back	Sticker	Removal
			
004	Bumper / Back Painted : Yes	Improper Repair	Acceptable
			
005	Door sill / Back Right	Scratched	Acceptable
			


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

006	Door / Front Right	Scratched	Acceptable



007	Bumper moulding / Front Painted : No	Non Compliant	Replace



Loose Items

- [x] Triangle
- [x] Rear parcel shelf
- [x] Spare Key
- [x] First aid kit
- [x] Conformity certificate
- [x] Safety vest
- [x] Registration certificate owner
- [x] Registration certificate

Main set of tyres

Front Left	PIRELLI	205/55/16 Summer	4 mm
Front Right	PIRELLI	205/55/16 Summer	4 mm
Back Left	BRIDGESTONE	205/55/16 Summer	4 mm
Back Right	BRIDGESTONE	205/55/16 Summer	4 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left



Rear left


Boot opened


Rear right


Rear passenger compartment



Dashboard from rear seat



Front passenger compartment



Front right



Odometer


Navigation



Spare Tyre


Cable


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Vin



Other




Other



Other



Personal Data / - / Non Compliant



Personal Data / - / Non Compliant



Door housing seal / Back Left / Non Compliant



Door housing seal / Back Left / Non Compliant



Rear windscreen / Back / Sticker



Bumper / Back / Improper Repair



Door sill / Back Right / Scratched



Door / Front Right / Scratched



Bumper moulding / Front / Non Compliant



Bumper moulding / Front / Non Compliant



Bumper moulding / Front / Non Compliant

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.