



TOYOTA Yaris: 2656-MPX

Vinnumber:	YARKBAC3500202939	Versionname:	1.5 120H Business Plus berlina con portón 85kw 5P automática
First Registrationdate:	24/04/2024	Fiscalpower:	
Expertise Mileage:	94039	Power Kw:	
Bodytype:	Berline	Body colour:	White
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:			
Fueltype:	Hybrid		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options

Number of keys total:	2	Radio:	
Number keys remote:	1	Central consol F:	
Windows electric F:		Luggage cover:	
Cruise Control:			
Steering wheel multifunctional:			
Radio multimedia:			
Type of climate control:	Autom climate control		

Tyres

185/65/15/88 H				
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				185/65 R 15 88 H
Tyre size FR				185/65 R 15 88 H
Tyre size RL				185/65 R 15 88 H
Tyre size RR				185/65 R 15 88 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
--------------	------------	-------	------------

Backrest cover FL, Tear, Replace



Steering wheel, Worn, Replace



Seat cover FL, Burned, Replace



Floor covering FL, Tear, Replace



Interior, Not original part, Acceptable



Registration document, Missing, Repair/replace (lump sum)



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill L, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Windscreen, Broken, Replace



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Outer sill R, Scratch(es), Repair and paint (complete)



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Door FR, Scratch(es), Repair and paint (complete)



Boot carpet, Tear, Replace



Rear panel, Dent(s) and scratch(es), Repair and paint (complete)



Internal boot lining R, Scratch(es), Replace



Internal boot lining L, Scratch(es), Replace



Bumper spoiler Rear, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check



Bodywork, Glue residues, Remove lettering



Roof rail L, Casse, Replace



Roof, Scratch(es), Repair and paint (complete)

