

MACADAM



MERCEDES CLA SHOOTING BRAKE: 1WVX224

Vinnumber:	WDD1186841N065837	Versionname:	CLA 180 Business Solution
First Registrationdate:	1/10/2019	Fiscalpower:	
Expertise Mileage:	79660	Power Kw:	100
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3507
Fueltype:	Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather and alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

225/45/18/92 H				
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/45 R 18 92 H
Tyre size FR				225/45 R 18 92 H
Tyre size RL				225/45 R 18 92 H
Tyre size RR				225/45 R 18 92 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2562,11
Interior, Dirty, Forfeit	75,00



Door panel RL, Scratch(es), Smart repair 116,69



Bumper F, Dent(s) and scratch(es), Repair and paint (complete) 415,60



Alloy rim RL polished, Scratch(es), Repair and paint (complete) 204,21



Step L, Dent(s) and scratch(es), Repair and paint (complete) 161,81



Door FL, Dent(s), Repair and paint (complete) 445,79



Sill trim L, Scratch(es), Acceptable 0,00



Alloy rim FL polished, Scratch(es), Acceptable 0,00



Luggage compartment cover, Missing, Replace 276,20



Bumper R, Scratch(es), Repair and paint (complete) 296,58



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 204,21



Alloy rim RR polished, Scratch(es), Repair and paint (complete) 204,21



Step R, Dent(s), Repair and paint (complete) 161,81

