



Expertise

Protocol number: 46679097
Order No. / Reference: 26565870
Inspection date: 15 Jul 2026

Manufacturer: Mercedes-Benz
VIN: W1N4N1AB2RJ565083

Model: GLA 180 d 8G-DCT Entry



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz GLA 180 d 8G-DCT Entry	
Vehicle Identification number	W1N4N1AB2RJ565083
Mileage (Read)	74,264 km
First registration	15 Dec 2023
Number of holders	1
Next periodical technical inspection	12/2026
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	85 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Mountaingrau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	316 Tag(e)
Last service on / at	05/2026 at 74,197 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY516388
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / ATH 00075		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,160 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 99V	Summer tyres on Light alloy	Continental	5mm / 5mm
2)	215/65 R17 99V	Summer tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 99H	Winter tyres on Light alloy	Michelin	6mm / 6mm
2)	215/65 R17 99H	Winter tyres on Light alloy	Michelin	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in center console with roller blind
- Adaptive Highbeam Assist
- Airbag for driver and front passenger
- Airbag: Side airbag for driver and front passenger
- Active Brake Assist
- Anti-lock braking system (ABS)
- Center console armrest for driver and front passenger with integrated storage compartment
- Heated exterior mirrors (left and right), electrically adjustable from inside
- Roof rails in polished aluminum
- Double cup holder
- Third brake light in LED technology
- ECO start/stop function
- Electronic Stability Program (ESP)
- Electric windows (4-way)
- Windscreen laminated glass
- Luggage net on driver and passenger seatbacks
- Transmission: 8G-DCT dual-clutch automatic transmission, 8-speed
- Interior headliner fabric crystal grey
- Mechanical child safety lock
- Communication module (LTE) for the use of Mercedes me connect services
- Steering wheel: Multifunction sports steering wheel in leather
- Steering: Direct steering
- Navigation accessories: Extended MBUX functions
- Navigation: Hard disk navigation
- Navigation: MBUX Navigation Premium
- Package: Cargo space
- Package: Seating comfort
- Upholstery: ARTICO leatherette/fabric
- Radio accessories: CENTRAL MEDIA DISPLAY 10.25"
- Tire pressure monitoring system
- Wheels: 43.2 cm (17") light alloy wheels in a 5-twin-spoke design
- GLA-Class seat belts
- Seats: Rear seat backrests foldable
- Cruise control
- Pre-installation for digital key handover
- Electronic immobilizer
- Central locking
- ADAPTIVE BRAKE with HOLD function, hill start assist, pre-filling and drying brakes in wet conditions
- Airbag: Kneebag for driver
- Airbag: Windowbags
- Active Lane Keeping Assist
- Traction control (ASR)
- ATTENTION ASSIST
- Automatic passenger airbag deactivation
- Outdoor temperature display
- Basic services
- Diesel particulate filter
- Tachometer
- DYNAMIC SELECT
- Door sills with "Mercedes-Benz" lettering
- Chassis: Comfort chassis with lowered suspension
- electric parking brake
- Velour floor mats
- Speed Limit Assistant
- Rear window wiper with intermittent function
- Heated rear window with timer
- ISOFIX child seat anchorages with Top Tether in the rear
- Climate: THERMATIC automatic climate control
- Headrests 5-way
- LED High Performance Headlights
- Steering column mechanically adjustable in height and length
- Mercedes-Benz emergency call system
- Navigation accessories: Pre-installation for Live Traffic Information
- Package: Entry
- Package: Light and Visibility Package
- Package: USB Package Plus
- Radio: MBUX multimedia system
- Radio accessories: Digital radio
- Remote Services
- Rear view camera
- Windscreen wipers with rain sensor
- Seats: Comfort seats
- Heated seats for driver and front passenger
- TIREFIT with tire inflation compressor
- High-visibility vest for drivers
- Heat-insulating glass, green all around
- Decorative elements Star Pattern



Extra equipment

- 1 set of WKR 17 inch 5 spoke aluminum wheels
- Package: Entry Advanced (4-way lumbar support - Mirror package (automatically dimming interior mirror, electrically folding exterior mirrors) - Parking package with reversing camera (Active Parking Assist with PARKTRONIC) - EASY-PACK tailgate (electrically opening and closing tailgate, switch for electrically opening the tailgate in the driver's door, switch for electrically closing the tailgate at the bottom edge of the tailgate, manual load compartment cover))
- Fully digital instrument display (high-resolution 10.25" display)
- Paint finish: Metallic (according to sample card)
- Package: Winter Package (heated steering wheel - heated seats for driver and front passenger - heated windshield washer system)
- Phone accessories: Smartphone integration (consisting of Apple CarPlay and Android Auto)
- Cargo net (This feature protects you from loose items in the luggage compartment. The cargo net is very easy to use. You can attach or remove it in just a few steps.)
- Traffic Sign Assistant 513

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - rear left side	Door - Scratch(es) - Smart repair
2	Door - rear right side	Door - Dent / paintcoat damage - Smart repair

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - Scratch(es) - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Interior	Interior - Soiled - No deduction
5	Rear bumper	Rear bumper - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Damage 1: Door - rear left side: Door - Scratch(es) - Smart repair



Damage 1: Door - rear left side: Door - Scratch(es) - Smart repair



Damage 1: Door - rear left side: Door - Scratch(es) - Smart repair



Damage 2: Door - rear right side: Door - Dent / paintcoat damage - Smart repair



Damage 2: Door - rear right side: Door - Dent / paintcoat damage - Smart repair



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1N4N1AB2RJ565083

Hersteller / Modell: MERCEDES-BENZ MERCEDES-BENZ GLA 180 d 8G-DCT Entry

Datum	KM-Stand	Beschreibung
26.05.2026	74.197	Regelwartungsdienst
30.01.2025	55.636	Regelwartungsdienst
02.07.2024	27.744	Regelwartungsdienst