



RENAULT CLIO: GK-468-LQ

Vinnumber:	VF1RJA00669640310	Versionname:	RENAULT CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)
First Registrationdate:	9/11/2022	Fiscalpower:	
Expertise Mileage:	131669	Power Kw:	103
Bodytype:	Berline	Body colour:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Hybrid	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Seat cover lining	Lining Other
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

195/55/16/87 H				
Summer tyres:	Fr.L.	Continental: 75%	Fr.R.	Continental: 70%
	Re.L.	Continental: 80%	Re.R.	Continental: 80%
Tyre profile depth FL				3.5
Tyre profile depth FR				3.7
Tyre profile depth RL				3.1
Tyre profile depth RR				2.9
Tyre size FL				195/55 R 16 87 H
Tyre size FR				195/55 R 16 87 H
Tyre size RL				195/55 R 16 87 H
Tyre size RR				195/55 R 16 87 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Seat cover FR, Stain, Cleaning



Seat cover R, Stain, Cleaning



Tyre FL, Out of tolerance, Replace



Tyre RL, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Tyre FR, Out of tolerance, Replace



Bumper F, Difference in color, Paint



Outer sill R, Scratch(es), Polish



Internal boot lining R, Broken, Replace



Bumper R, Scratch(es), Acceptable



Bodywork, Not original part, Sticker removal small



Historique Maintenance

Immatriculation: **GK-468-LQ**Date de 1ère immatriculation: **09/11/2022**Modèle: **Renault CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
24/03/2026	124.893	AGENCE M&V AUTOMOBILES	REVISION
	0		RECYCLAGE
	0		PILE DE CLE RPLT
	0		BALAI ESSUIE GLACE AR
	0		BALAIS ESSUIE GLACE AV
	0		LIQUIDE DE FREIN
19/03/2026	124.893	AGENCE M&V AUTOMOBILES	PILE DE CLE RPLT
	0		REVISION
	0		LIQUIDE DE FREIN
	0		BALAIS ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		PILE DE CLE RPLT
	0		RECYCLAGE
22/10/2025	107.880	CONTITRADE FRANCE	REPARATION DE ROUE
02/09/2025	102.458	FLEET SOLUTIONS FRANCE	REPLACEMENT PNEUS ETE
09/04/2025	93.590	AGENCE M&V AUTOMOBILES	RECYCLAGE
	0		REVISION ET CLIM
03/10/2024	71.209	LPM AUTO	JANTE RPLT
03/10/2024	71.209	LPM AUTO	ESSAI
	0		RECYCLAGE
	0		DIAG
02/10/2024	71.036	CONTITRADE FRANCE	REPARATION DE ROUE
09/07/2024	63.347	CONTITRADE FRANCE	REPLACEMENT PNEUS ETE
19/06/2024	62.972	AGENCE M&V AUTOMOBILES	RECYCLAGE
	0		BALAIS ESSUIE GLACE AV
	0		REVISION
	0		BALAI ESSUIE GLACE AR
09/01/2024	44.951	AGENCE M&V AUTOMOBILES	REPARATION DE ROUE
18/10/2023	33.987	AGENCE M&V AUTOMOBILES	REPARATION DE ROUE
28/09/2023	31.032	AGENCE M&V AUTOMOBILES	REPLACEMENT PNEUS ETE
	0		REPLACEMENT PNEUS ETE
28/09/2023	31.032	AGENCE M&V AUTOMOBILES	RECYCLAGE

Historique Maintenance

Immatriculation: **GK-468-LQ**

Date de 1ère immatriculation: **09/11/2022**

Modèle: **Renault CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
	0		REVISION ET CLIM