

Vehicle details

VIN	YSM4ZPAA9 TF430557	Registration date	10/10/2025	Exterior Color	Snow Matte
Brand	Polestar	Licence Plate	N/A	Odometer	9 276 km
Model	Polestar 4 PA / 200 kW (272 PS)	Condition of the car	Mit Schaden		
Pre-damage		Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details




Removable element

Spare wheel kit	✓
Toolkit	✓
Triangle	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓

Technical Document

User manual	✓
Warranty booklet	✓
Log books	✓
First aid kit	✓
Inspektion	✓
Ladekabel Starkstrom-Steckdose	✓

Tyres



Exterior

1		Part	Door	Repair Time	0.60	Part Cost	-
		Position	Back left	Repair Cost	54.00€	Net Cost	54.00€
		Damages	Dented - Smart repair	Paint Time	-		
		Comments	-	Paint cost	-		
				Flat Rate	54.00€		
2		Part	Tailgate / Boot door	Repair Time	0.60	Part Cost	-
		Position	-	Repair Cost	54.00€	Net Cost	54.00€
		Damages	Dented - Smart repair	Paint Time	-		
		Comments	-	Paint cost	-		
				Flat Rate	54.00€		
3		Part	Wing	Repair Time	0.60	Part Cost	-
		Position	Back right	Repair Cost	54.00€	Net Cost	54.00€
		Damages	Dented - Smart repair	Paint Time	-		
		Comments	-	Paint cost	-		
				Flat Rate	54.00€		