



**CITROËN Jumper: 3730-LNJ**

Vinnumber:	<b>VF7YDBNFC12R57071</b>	Versionname:	<b>Citroen BlueHDi 103KW (140CV) Furg.35 Heavy L4H3 furgón 103kW 4P manual</b>
First Registrationdate:	<b>26/03/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>173875</b>	Power Kw:	
Bodytype:	<b>Transporter</b>	Body colour:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Steel</b>
Transmission:			
Fueltype:	<b>Diesel</b>		
Engine functioning:	<b>Yes</b>		
Battery functioning:	<b>Yes</b>		
Vehicle running:	<b>Yes</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Type of rims (mounted):	<b>Steel</b>		
Certificate of Conformity:	<b>No</b>		
Category:	<b>Light Commercial Vehicle</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Number of keys total:	<b>1</b>	Rear parking sensors
Number keys remote:	<b>1</b>	
Windows electric F:		
Steering wheel multifunctional:		
Radio multimedia:		
Type of climate control:	<b>Manual climate control</b>	

**Tyres**

<b>215/75/16/114 R</b>				
Summer tyres:	Fr.L.	<b>Goodyear: 7 mm</b>	Fr.R.	<b>Goodyear: 7 mm</b>
	Re.L.	<b>Goodyear: 7 mm</b>	Re.R.	<b>Goodyear: 7 mm</b>
Tyre profile depth FL				<b>7.0</b>
Tyre profile depth FR				<b>7.0</b>
Tyre profile depth RL				<b>7.0</b>
Tyre profile depth RR				<b>7.0</b>
Tyre size FL				<b>215/75 R 16 114 R</b>
Tyre size FR				<b>215/75 R 16 114 R</b>
Tyre size RL				<b>215/75 R 16 114 R</b>
Tyre size RR				<b>215/75 R 16 114 R</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>259</b>
Tyre make FR				<b>259</b>
Tyre make RL				<b>259</b>
Tyre make RR				<b>259</b>

**Assistance equipment**

Spare wheel:	<b>Yes</b>	Jack:	<b>Yes</b>
--------------	------------	-------	------------

Seat cover FR, Hole, Repair/replace (lump sum)



Door panel FR, Scratch(es), Repair/replace (lump sum)



Seat cover FL, Hole, Repair/replace (lump sum)



Steering wheel, Worn, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



MOT certificate, Missing, Repair/replace (lump sum)



Ignition key, Missing, Repair/replace (lump sum)



Mirror side repeater L, Scratch(es), Replace



Wing RL, Dent(s), Repair and paint (complete)



Fender moulding RL, Missing, Replace



Bumper moulding FR, Missing, Replace



Bumper F, Scratch(es), Paint



Rear light R, Broken, Acceptable



Wing RR, Dent(s), Repair and paint (complete)



Sliding door R, Scratch(es), Paint



Door FR, Scratch(es), Paint



Outside rear-view mirror R, complete, Broken, Replace



Boot door panel RL, Dent(s), Repair and paint (complete)



Boot door panel RR, Dent(s), Repair and paint (complete)



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Tyres, No damage, Check





Bodywork, Glue residues, Remove lettering



Bodywork, Accident, Check





