



VOLVO XC60: FM-298-ZL

Vinnumber:	LYVUZBMVDL8511001	Versionname:	VOLVO XC60 T8 TWE 390 Geartronic 8 Business Exe VP [5P] bva 8-390CH-17cv (SUV)	
First Registrationdate:	10/01/2020	Fiscalpower:		
Expertise Mileage:	173296	Power Kw:	287	
Bodytype:	Off-road	Body colour:	Black	
Gearbox:	Automatic	Paint type:	Metallic	
Transmission:	Front	Interior colour:	Beige	
Fueltype:	Hybrid	Type of rims (mounted):	Aluminium	
Engine functioning:	Yes	Dashboard color:	Black	
Battery functioning:	Yes			
Vehicle running:	Yes			
Number of doors:	5			
Number of seats:	5			
Number head rests:	5			
Type of rims (mounted):	Aluminium			
Category:	Passenger Car			

Options

Number of keys total	1	Radio	
Number keys remote	1	Sun Roof electric	
GPS big screen color		Panoramic roof	
Windows electric F		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Headlights Xenon/LED/Laser	
Steering wheel leather		Front parking sensors	
Type of climate control	Autom climate control	Rear parking sensors	
		Rear view camera	
		Seat cover lining	Lining Leather

Tyres

	235/60/18/107 H			
Summer tyres:	Fr.L.	Michelin: 65%	Fr.R.	Michelin: 55%
	Re.L.	Michelin: 55%	Re.R.	Michelin: 55%
Tyre profile depth FL				4.0
Tyre profile depth FR				4.6
Tyre profile depth RL				4.5
Tyre profile depth RR				4.5
Tyre size FL				235/60 R 18 107 H
Tyre size FR				235/60 R 18 107 H
Tyre size RL				235/60 R 18 107 H
Tyre size RR				235/60 R 18 107 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Jack

Yes

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Wing FL, Dent(s), Repair and paint (complete)



Door FL, Scratch(es), Paint



Door RL, Scratch(es), Paint



Bonnet, Dent(s), Repair and paint (complete)




Bumper F, Scratch(es), Paint



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Wing FR, Dent(s), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Paint



Historique Maintenance

Immatriculation: **FM-298-ZL** Date de 1ère immatriculation: **10/01/2020**

Modèle: **Volvo XC60 T8 TWE 390 Geartronic 8 Business Exe VP [5P] bva 8-390CH-17cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
15/05/2025	142.544	CAP NORD AUTOMOBILES	REVISION
	0		RECYCLAGE
	0		BALAI ESSUIE GLACE AR
	0		LIQUIDE DE FREIN
11/04/2024	102.913	CAP NORD AUTOMOBILES	DIVERS CARROSSERIE
	0		REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV
	0		DIVERS
	0		FEU ARG RPLT
02/04/2024	101.686	CAP NORD AUTOMOBILES	REPLACEMENT PNEUS ETE
22/06/2023	70.746	CAP NORD AUTOMOBILES	REVISION ET CLIM ET AIR ET BOUGIES
	0		LIQUIDE DE FREIN
	0		RECYCLAGE
28/02/2023	63.059	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
28/02/2023	63.059	EUROFLEET TYRES AND SERVICES	FERMETURE DOSSIER TECHNIQUE
26/10/2021	31.604	CAP NORD AUTOMOBILES	REVISION ET CLIM
16/09/2021	29.848	CAP NORD AUTOMOBILES	REPLACEMENT PNEUS ETE