



**Skoda Superb:**

Vinnumber:	<b>TMBJW9NP2M7065443</b>	Versionname:	
First Registrationdate:	<b>1/06/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>88589</b>	Power Kw:	
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>2305</b>
Fueltype:	<b>Hybrid Petrol</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Number of keys total	<b>3</b>	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Sun Roof electric	
Seats F heated		Panoramic roof	
Radio multimedia		Luggage cover	
Type of headlighting	<b>Headlighting LED</b>	Front parking sensors	
Type of GPS	<b>GPS big screen color</b>	Rear parking sensors	
Type of Lining	<b>Lining artificial leather</b>	Type of Tow bar	<b>Tow bar collapsible</b>
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

**Tyres**

205/40/19/92 H				
Summer tyres:	Fr.L.	<b>Pirelli: 5 mm</b>	Fr.R.	<b>Pirelli: 5 mm</b>
	Re.L.	<b>Pirelli: 5 mm</b>	Re.R.	<b>Pirelli: 5 mm</b>
Tyre profile depth FL				<b>5.0</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>205/40 R 19 92 H</b>
Tyre size FR				<b>205/40 R 19 92 H</b>
Tyre size RL				<b>205/40 R 19 92 H</b>
Tyre size RR				<b>205/40 R 19 92 H</b>
Tyre type FL				<b>All seasons</b>
Tyre type FR				<b>All Seasons</b>
Tyre type RL				<b>All seasons</b>
Tyre type RR				<b>All Seasons</b>
Tyre make FL				<b>264</b>
Tyre make FR				<b>264</b>
Tyre make RL				<b>264</b>
Tyre make RR				<b>264</b>

**Assistance equipment**

Number of charging cables (normal)	<b>1</b>
Number of charging cables (rapid charge)	<b>1</b>

Total cost ex VAT	<b>525,11</b>
Backrest cover FL, Damaged, Smart repair	<b>116,69</b>



Bumper F, Scratch(es), Acceptable 0,00



Alloy rim RL polished, Scratch(es), Acceptable 0,00



Door FL, Bad repair, Check 0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 204,21



Bumper R, Bad repair, Check 0,00



Rear window, Scratch(es), Polish 0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 204,21



Door FR, Dent(s) and scratch(es), Acceptable 0,00



Alloy rim RR polished, Rust, Acceptable 0,00

