



Ford Mustang: L513PR

Vinnumber:	WF0TK1EM4MMA17049	Versionname:	Mustang Mach-E 190kW/ 75,7kWh RWD automaat
First Registrationdate:	14/07/2021	Fiscalpower:	
Expertise Mileage:	131851	Power Kw:	190
Bodytype:		Body colour	Shadow Black
Gearbox:	Automatic	Paint type	Opaque
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	451
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	Yes		

Options

Number of keys total	2	Lining leather
GPS		Rear parking sensors
Autom climate control		Rear view camera
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 60 / 18 / 104 / V / Aluminium	6,1 mm	Continental	Summer
	Right	225 / 60 / 18 / 104 / V / Aluminium	6,1 mm	Continental	Summer
Rear	Left	225 / 60 / 18 / 104 / V / Aluminium	5,2 mm	Continental	Summer
	Right	225 / 60 / 18 / 104 / V / Aluminium	6,1 mm	Continental	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------


Service, Maintenance, Execute



Interior covering A pillar R, Stain, Cleaning



Roof liner, Stain, Cleaning



Wing FL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Bonnet, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bumper spoiler F, Scratch(es), Replace



Bumper FM, Scratch(es), Repair and paint (complete)



Fuel cap cover, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Wheel arch cover RR, Scratch(es), Replace



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Boot lid covering R, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Roof, Hail damage, Paintless dent repair (hail)



Kenteken	L513PR
Merk Model	Ford Mustang Mach-E 198kW/ 75,7kWh RWD automaat
Brandstofsoort	Elektrisch
Datum deel1	14-07-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
16-07-25	104.010	APK
16-07-25	104.010	Onderhoudsbeurt
16-07-25	104.010	Remblokken achterzijde
16-07-25	104.010	Remvloeistof
16-07-25	104.010	Sleutelbatterij
12-11-24	88.269	Instap verlichting
12-11-24	88.269	Ruitenwischerblad(en) achterzijde
12-11-24	88.269	Ruitenwischerblad(en) voorzijde
25-04-24	74.928	Aandrijfas
27-07-23	52.853	Onderhoudsbeurt
27-07-23	52.853	Remvloeistof
27-07-23	52.853	Ruitenwischerblad(en) voorzijde