



PEUGEOT 5008: 9005-MDZ

Vinnumber:	VF3MRHNSMPS012888	Versionname:	1.2 PureTech 96KW S&S Allure Pack todoterreno
First Registrationdate:	22/02/2023	Fiscalpower:	96kW 5P manual
Expertise Mileage:	78945	Power Kw:	
Bodytype:	SUV	Body colour	Dark Brown
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:			
Fueltype:	Petrol		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	7		
Number head rests	7		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Number of keys total	2	Radio
Number keys remote	2	Central consol F
GPS big screen color		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		Roof bar alu
Steering wheel multifunctional		Roof rack
Steering wheel leather		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

	225/55/18/102 V			
Summer tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				225/55 R 18 102 V
Tyre size FR				225/55 R 18 102 V
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				257
Tyre make FR				257
Tyre make RL				257
Tyre make RR				257

Assistance equipment

Repair kit	Yes
Rear bulkhead lining, Scratch(es), Replace	



Interior, Dirty, Cleaning



Boot lid covering R, Scratch(es), Replace




Registration document, Missing, Repair/replace (lump sum)



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)




Wing FL, Scratch(es), Acceptable



Mirror side repeater L, Broken, Replace



Door FL, Scratch(es), Repair and paint (complete)



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Wing trim RL, Scratch(es), Paint



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bumper spoiler F, Scratch(es), Polish



Bumper spoiler F, Scratch(es), Paint



Wing FR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Paintless dent repair



Bumper moulding RL, Scratch(es), Repair and paint (complete)



Internal boot lining L, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check

