



Ford Mustang: L091JH

Vinnumber:	WF0TK1E71MMA15057	Versionname:	Mustang Mach-E 210kW/ 98,8kWh Extended RWD automaat
First Registrationdate:	4/06/2021	Fiscalpower:	
Expertise Mileage:	169989	Power Kw:	210
Bodytype:		Body colour	Metaallak: Space White
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	504
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	Yes		

Options

Number of keys total	2	Lining leather
GPS		Rear parking sensors
Autom climate control		Rear view camera
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 60 / 18 / 104 / H / Aluminium	6,7 mm	Bridgestone	Winter
	Right	225 / 60 / 18 / 104 / H / Aluminium	6,4 mm	Bridgestone	Winter
Rear	Left	225 / 60 / 18 / 104 / H / Aluminium	4,3 mm	Bridgestone	Winter
	Right	225 / 60 / 18 / 104 / H / Aluminium	4,5 mm	Bridgestone	Winter

Assistance equipment

Number of charging cables (rapid charge)	1
--	---

Service, Maintenance, Execute



Door FL, Dent(s), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Crack, Repair and paint (complete)



Bumper moulding F, Broken, Replace



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Kenteken	L091JH
Merk Model	Ford Mustang Mach-E 216kW/ 98,8kWh Extended RWD automaat
Brandstofsoort	Elektrisch
Datum deel1	04-06-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
09-01-26	150.403	Onderhoudsbeurt
09-01-26	150.403	Remvloeistof
09-01-26	150.403	Ruitenwischerblad(en) achterzijde
09-01-26	150.403	Ruitenwischerblad(en) voorzijde
09-01-26	150.403	Sleutelbatterij
30-06-25	128.025	APK
11-11-24	107.232	Accu
28-10-24	0	Accu
15-02-24	81.757	Onderhoudsbeurt
15-02-24	81.757	Remvloeistof
15-02-24	81.757	Ruitenwischerblad(en) achterzijde
15-02-24	81.757	Ruitenwischerblad(en) voorzijde
10-08-22	37.582	Vervanging band
23-05-22	30.734	Onderhoudsbeurt
09-11-21	16.529	Reparatie band(en)