MACADAM







Peugeot 2008 (UKL): 2EJW942

Vinnumber:	**VR3USHNKKPJ835979**	Versionname:	**2008 Active Pack 1.2 Puretech S&S 100pk/cv 5p**
First Registrationdate:	**26/10/2023**	Fiscalpower:	
Expertise Mileage:	**39717**	Power Kw:	**74**
Bodytype:		Type of rims (mounted)	**Steel**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**plus 11200 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**215/65/16/98 H**			
	Fr.L.	**Goodyear: 3 mm**	Fr.R.	**Goodyear: 4 mm**
	Re.L.	**Goodyear: 4 mm**	Re.R.	**Goodyear: 4 mm**

Tyre profile depth FL	**3.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**215/65 R 16 98 H**
Tyre size FR	**215/65 R 16 98 H**
Tyre size RL	**215/65 R 16 98 H**
Tyre size RR	**215/65 R 16 98 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Engine insulation, Hole, Replace





Bumper F, Scratch(es), Spot repair





Fog lamp R, Scratch(es), Acceptable




Door FL, Dent(s), Paintless dent repair




Door RL, Scratch(es), Acceptable




Bumper trim R, Scratch(es), Acceptable




Bumper R, Scratch(es), Acceptable




Wing RR, Scratch(es), Acceptable




Wheel cover RR, Scratch(es), Acceptable




Door RR, Scratch(es), Acceptable





Outside rear-view mirror housing R, Scratch(es), Acceptable




Wheel cover FR, Scratch(es), Replace





Wing FR, Bad repair, Spot repair





Onderhoudshistorie van: VR3USHNKKPJ835979

ALPHABET

Kenteken	2EJW942
Merk Model	Peugeot 2008 Active Pack 1.2 Puretech S&S 100pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	10/26/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
11/12/25	31,003	luchtfilter interieur	Vervangen
11/12/25	31,003	oliezeef	Vervangen
11/12/25	31,003	onderhoud 2e jaar	Uitvoeren
11/12/25	31,003	remvloeistof	Vervangen
11/13/24	12,063	luchtfilter interieur	Vervangen
11/13/24	12,063	oliezeef	Vervangen
11/13/24	12,063	onderhoud 1e jaar	Uitvoeren
11/13/24	12,063	ruitenwisserrubber vooraan	Vervangen