MACADAM ITALY S.R.L.

Piazza Belgioioso, 2 - 20121 Milano (MI)

Tel. - Fax

Piva: 12729790969

Report No.	Expert's report for	Type of insurance
	Alphabet Italia	Perizia

Policyholder	Opposite party	Opposite party company

Operation	Claim number	Code / Agency	Date accident
2026			22/10/2026

Expert code	Adjuster code	Policy number	Injured person can recover the VAT

Date assignment	Date first survey	Place	C/O	Repairs	Photo	Lien in favor of	Expiry date
22/10/2026		GENOVA	VAR				

Ownership certificate: Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN) — Formerly plate:

Lessee / Co-owner — Date of overhaul:


Vehicle (Brand - Model - Version)	Plate	Vin Chassis	First Registration
SEAT Leon 3ª serie Leon 2.0 TDI 150 CV DSG ST FR	GC810GH	VSSZZZ5FZLR104539	31/07/2020

Usage status	Km	Tyres %	Color	Type of enamel	Consistency of damage	Type of Expert's report
NON CONOSCIUTO	98069	50	BIANCO	METALLIZED		NOT DEFINITIVE

Equipment

Approval code	For commercial vehicles	Carrying Qls	Tare,Q	Wheelbase	Seats No.	Axles
		0	0		0	0

Commercial value (C)	Wrecked car value	Value by difference	Ancillary expenses



	Damaged items / restoration operations			SR		LA		VE		ME	D.M. S.C.	Costs of spare parts * (VAT excluded)	
				Dif	Time	Dif	Time	Dif	Time	Time			
1	5F4867012BVHI	Internal panel of front door	R	S		S		S					
1	3C0881253A9B9	Front seat longitudinal regulating lever	L	S		S		S					
1	5F0853665H9B9	Front bumper side grille	L	S		S		S					
1	5F0853666H9B9	Front bumper side grille	R	S		S		S					
1	5F9945105E	Rear reflector	L	S		S		S					
1	5F9817111	Roof		M		M		M					
1	5F9807421AEGRU	Rear bumper		M				M					
1	5F0823031C	Front bonnet		L		L		L					
1	5F0857537BGRU	External rear-view mirror cap	L	L				L					
1	5F0857538BGRU	External rear-view mirror cap	R	L				L					
1	5F0807221ADGRU	Front bumper		L				L					
1	5F9827024	Rear hatch		L		L		L					
1	Codice Ricambio	Parabrezza PRM											
1	Codice Ricambio	Vano porta post. PRM	R										
1	Codice Ricambio	Pannello int. portellone post. PRM											
1	Codice Ricambio	Igienizzante tessuto											
1	Codice Ricambio	Rettifica cerchi in lega x4											
1	Codice Ricambio	Porta ant. PRM	L										
1	Codice Ricambio	Maniglia ant. PRM	L										
1	Codice Ricambio	Porta ant. PRM	R										
1	Codice Ricambio	Porta post. PRM	R										
1	Codice Ricambio	Maniglia ant. PRM	R										
1	Codice Ricambio	Parafango post. PRM	L										
1	Codice Ricambio	Parafango post. PRM	R										
1	Codice Ricambio	Volante PRM											

New for old value (N)

Remarks

PNEUM. PIRELLI 225/40R18.
VHL GRANDINATO.

Prepared by A.M.G. Software di Torino - Ph. (011) 599.870 - Fax (011) 595.323 - www.amgsoftware.it - e-mail info@amgsoftware.it