

INSPECTION REPORT

End of contract

GENERAL INFO

File	316187
License plate	2ABJ621
Vehicle identification number	WBA11AG030CG49335
Dossier	2020344014
Make	BMW 530e 200kW Aut
Mileage	127082
First registration	09/02/2021
client availability date	24/06/2026
inspectionDate	01/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	Y
38	Front Bonnet / Insulation / Replace	N
80	Door Front Left // Smart Repair Small	Y
100	Door Rear Left // Smart Repair Small	Y
110	Wing Rear Left // Smart Repair Small	Y
124	Light / Rear left / Replace	Y
133	Bumper Rear // Painting	Y
174	Light / Rear Right / Replace	Y
183	Wing Rear Right // Painting	Y
196	Door Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	Y
216	Door Front Right // Polish	Y
240	Headlight / Front Right/ Repair	N
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	Y
614	Front Left Door Interior Coating // Replace Completely	Y
631	Rear Left Door Interior Coating // Repair	N

Damage Pictures




Front Left Door Interior Coating // Replace Completely-scratch



Bumper Rear // Painting-scratch



Light / Rear left / Replace-scratch




Light / Rear Right / Replace-scratch




Wing Rear Right // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch



Door Rear Right // Polish-scratch



Door Front Right // Polish-scratch



Headlight / Front Right/ Repair-scratch




Bumper Front // Polish-scratch



Wheel Alloy Front Left // Repair-scratch




Door Front Left // Smart Repair Small-scratch



Rear Left Door Interior Coating // Repair-scratch



Door Rear Left // Smart Repair Small-dent



Wing Rear Left // Smart Repair Small-dent



Rocker Panel Right // Smart Repair Medium-dent



Front Bonnet / Insulation / Replace-tear