



Ford Mustang: L719PD

Vinnumber:	WF0TK1E78MMA13922	Versionname:	Mustang Mach-E 210kW/ 98,8kWh Extended RWD
First Registrationdate:	5/07/2021	Fiscalpower:	automaat (NEDC)
Expertise Mileage:	149950	Power Kw:	210
Bodytype:		Body colour	Premium Metaallak: Carbonized Grey
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	1085
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Lining leather
GPS		Rear parking sensors
Autom climate control		Rear view camera
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 60 / 18 / 100 / V / Aluminium	6,2 mm	Bridgestone	Summer
	Right	225 / 60 / 18 / 100 / V / Aluminium	6,5 mm	Bridgestone	Summer
Rear	Left	225 / 60 / 18 / 100 / V / Aluminium	3,8 mm	Bridgestone	Summer
	Right	225 / 60 / 18 / 100 / V / Aluminium	3,5 mm	Bridgestone	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
--	---

Wing RL, Dent(s), Paintless dent repair



Door RL, Scratch(es), Repair and paint (complete)



Bumper F, Broken, Replace and paint



Bumper spoiler F, Broken, Replace



Bonnet, Stone chip(s), Repair and paint (complete)



Wing RR, Bad repair, Repair and paint (complete)



Door RR, Bad repair, Repair and paint (complete)



Door FR, Bad repair, Repair and paint (complete)



Wheel arch cover FR, Deformed / Strained, Replace



Kenteken	L719PD
Merk Model	Ford Mustang Mach-E 216kW/ 98,8kWh Extended RWD automaat
Brandstofsoort	Elektrisch
Datum deel1	05-07-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
18-03-26	142.838	Reparatie band(en)
29-10-25	136.612	APK
29-10-25	136.612	Onderhoudsbeurt
29-10-25	136.612	Remvloeistof
02-06-25	126.569	APK
29-03-24	107.900	Reparatie band(en)
29-03-24	107.906	Handrem mechanisme
28-11-23	97.846	Onderhoudsbeurt
28-11-23	97.846	Remvloeistof
28-11-23	97.846	Ruitenwisherblad(en) achterzijde
28-11-23	97.846	Ruitenwisherblad(en) voorzijde
31-03-23	76.874	Uitlijnen voor en achterwielen
17-02-22	26.602	Onderhoudsbeurt