MACADAM










## SKODA OCTAVIA: GE-017-MK

| | | | |
|---|---|---|---|
| Vinnumber: | **TMBAR7NX7NY061928** | Versionname: | **SKODA OCTAVIA 1.5 TSI 150 BVM6 Style VP [5P] bvm 6-150CH-8cv (bi-corps)** |
| First Registrationdate: | **3/02/2022** | Fiscalpower: | |
| Expertise Mileage: | **999999** | Power Kw: | **110** |
| Bodytype: | **Berline** | Body colour | **Blue** |
| Gearbox: | **MAN 6 VIT** | Paint type | **Metalic** |
| Transmission: | **Front** | Interior colour | **Black** |
| Fueltype: | **Petrol** | Type of rims (mounted) | **Aluminium** |
| Engine functioning | **No** | Dashboard color | **Black** |
| Battery functioning | **No** | | |
| Vehicle running | **No** | | |
| Number of doors | **5** | | |
| Number of seats | **5** | | |
| Number head rests | **5** | | |
| Type of rims (mounted) | **Aluminium** | | |
| Category | **Passenger Car** | | |

## Options

| | | | |
|---|---|---|---|
| Number of keys total | **2** | Central consol F | |
| Number keys remote | **2** | Front parking sensors | |
| Windows electric F | | Rear parking sensors | |
| Windows electric R | | Seat cover lining | **Lining Other Lining Leather** |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Steering wheel leather | | | |
| Type of climate control | **Autom climate control** | | |

## Tyres

| | | | | |
|---|---|---|---|---|
| Summer tyres: | **205/55/17/95 V** | | | |
| | Fr.L. | **Continental: 40%** | Fr.R. | **Continental: 40%** |
| | Re.L. | **Pirelli: 15%** | Re.R. | **Pirelli: 25%** |

| | |
|---|---|
| Tyre profile depth FL | **5.5** |
| Tyre profile depth FR | **5.7** |
| Tyre profile depth RL | **7.1** |
| Tyre profile depth RR | **6.6** |
| Tyre size FL | **205/55 R 17 95 V** |
| Tyre size FR | **205/55 R 17 95 V** |
| Tyre size RL | **205/55 R 17 95 V** |
| Tyre size RR | **205/55 R 17 95 V** |
| Tyre type FL | **Summer** |
| Tyre type FR | **Summer** |
| Tyre type RL | **All seasons** |
| Tyre type RR | **All Seasons** |
| Tyre make FL | **256** |
| Tyre make FR | **256** |
| Tyre make RL | **264** |
| Tyre make RR | **264** |

## Assistance equipment

Alloy rim FR, Scratch(es), Acceptable





Alloy rim RL, Scratch(es), Acceptable





Alloy rim FL, Scratch(es), Repair/replace (lump sum)





Wing FL, Scratch(es), Polish




Outside rear-view mirror housing L, Scratch(es), Paint




Door FL, Scratch(es), Paint




Bumper F, Scratch(es), Paint





Bonnet, Scratch(es), Paint





Door RR, Dent(s) and scratch(es), Repair and paint (complete)




Door FR, Scratch(es), Paint




Tailgate / Boot, Not functioning (well), Check



Tailgate / Boot, Dent(s) and scratch(es), Acceptable





**Bumper R, Scratch(es), Paint**






ALPHABET

# Historique Maintenance

Immatriculation: **GE-017-MK** Date de 1ère immatriculation: **03/02/2022**

Modèle: **Skoda OCTAVIA 1.5 TSI 150 BVM6 Style VP [5P] bvm 6-150CH-8cv (bi-corps)**

| Date | Kilométrage | Fournisseur | Descriptif |
|---|---|---|---|
| 06/02/2025 | 97.250 | CONTITRADE FRANCE | REMPLACEMENT PNEUS ETE |
| 12/12/2024 | 92.520 | SA COIGNIERES AUTOMOBILES | BALAIS ESSUIE GLACE AV |
| | 0 | | BALAI ESSUIE GLACE AR |
| | 0 | | LIQUIDE LAVE GLACE |
| | 0 | | LIQUIDE DE FREIN |
| | 0 | | PILE DE CLE RPLT |
| | 0 | | REVISION ET CLIM |
| 19/12/2023 | 62.863 | SA COIGNIERES AUTOMOBILES | PLAQUETTES AR RPLT |
| | 0 | | PLAQUETTES AV RPLT |
| | 0 | | REVISION |
| 23/01/2023 | 30.000 | SA COIGNIERES AUTOMOBILES | REVISION |