



To see full mileage history: Please use the URL in 'other notes'

Systeme d'assistance de conduite: commutateur de sensation de conduite ✓ éclaira ✓

Show more +

OTHER NOTES

Oil OK // Cooling fluid OK // Brake fluid OK // <https://public.car-pass.be/vhr/74f8a334-17e4811-a250-17eb19be8a0c>

CAR DAMAGES (4)

i Some damages have more than one photo to identify the imperfection

Front body Left body Rear body Right body