MACADAM










VOLKSWAGEN ID. BUZZ: GR-881-VK

Vinnumber:	**WV1ZZZEB7PH025507**	Versionname:	**VOLKSWAGEN ID. BUZZ 77 kWh 204ch Cargo VU [4P] bva 1-204CH-11cv (fourgon tÃ´lÃ©simple cabine)**
First Registrationdate:	**13/10/2023**	Fiscalpower:	
Expertise Mileage:	**81863**	Power Kw:	**150**
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**Automatic**	Paint type	**Opaque**
Transmission:	**Back**	Interior colour	**Black**
Fueltype:	**Electric**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**3**		
Number head rests	**3**		
Type of rims (mounted)	**Steel**		
Category	**Light Commercial Vehicle**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Headlights Xenon/LED/Laser	
Windows electric F		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Sliding door right-side	
Type of climate control	**Autom climate control**	Sliding door left-side	
		Seat cover lining	**Lining Other**

Tyres

Summer tyres:	**235/60/18/107 V**			
	Fr.L.	**Hankook: 30%**	Fr.R.	**Hankook: 30%**
	Re.L.	**Bridgestone: 45%**	Re.R.	**Bridgestone: 45%**

Tyre profile depth FL	**6.1**
Tyre profile depth FR	**6.2**
Tyre profile depth RL	**5.2**
Tyre profile depth RR	**5.2**
Tyre size FL	**235/60 R 18 107 V**
Tyre size FR	**235/60 R 18 107 V**
Tyre size RL	**255/55 R 18 109 V**
Tyre size RR	**255/55 R 18 109 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**260**
Tyre make FR	**260**
Tyre make RL	**255**
Tyre make RR	**255**

Assistance equipment

Air vent, mid-dashboard, Broken, Replace




Seat cover FL, Hole, Replace




Sun visor L, Broken, Replace




Interior, Dirty, Cleaning







Interior trim, Missing, Replace





Door seal RR, Tear, Replace




Door seal FR, Unclasped, Dismount/Mount




Interior trim, Unclasped, Dismount/Mount




Wheel cover RR, Missing, Replace




Wheel cover FR, Missing, Replace




Wheel arch cover FR, Broken, Replace




Side wall RL, Dent(s) and scratch(es), Repair and paint (complete)







Windscreen, Stone chip(s), Windscreen repair 2 stonechips







Shutter / cover F, Missing, Replace





Car body corner RR, Dent(s) and scratch(es), Repair and paint (complete)





Sill trim R, Deformed / Strained, Replace






Roof pillar R, Dent(s), Repair and paint (complete)







Door FR, Dent(s) and scratch(es), Repair and paint (complete)





Wing FR, Dent(s) and scratch(es), Replace and paint






Outside rear-view mirror housing R, Missing, Replace




Side repeater R, Broken, Replace




Charging cable (normal), Missing, Replace





Rear bulkhead lining, Scratch(es), Replace












Rubber seal for boot lid, Tear, Replace




Boot lid covering R, Scratch(es), Replace






Parking sensor R, Unclasped, Dismount/Mount





Shutter / cover R, Missing, Replace




Bumper corner RL, Scratch(es), Acceptable





Bodywork, Not original part, Remove lettering




Fuel cap cover, Broken, Replace





ALPHABET

Historique Maintenance

Immatriculation: **GR-881-VK** Date de 1ère immatriculation: **13/10/2023**

Modèle: **Volkswagen ID. BUZZ 77 kWh 204ch Cargo VU [4P] bva 1-204CH-11cv (fourgon tôlésimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
15/09/2026	80.682	PROFIL PLUS	REMPLACEMENT PNEUS ETE
12/07/2026	78.726	PROFIL PLUS	REMPLACEMENT PNEUS ETE
15/06/2026	77.536	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS ETE
			REMPLACEMENT PNEUS ETE
08/10/2025	56.311	PROFIL PLUS	REMPLACEMENT PNEUS 4 SAISONS
			REMPLACEMENT PNEUS 4 SAISONS
30/09/2025	54.875	AUTO.21 NOGENT-LE-PHAYE	REVISION ET CLIM
			BALAIS ESSUIE GLACE AV
			BALAI ESSUIE GLACE AR
			LIQUIDE DE FREIN
18/03/2025	34.163	PROFIL PLUS	REMPLACEMENT PNEUS 4 SAISONS
13/03/2025	33.629	PROFIL PLUS	REPARATION DE ROUE
04/12/2024	26.656	PROFIL PLUS	REMPLACEMENT PNEUS 4 SAISONS
02/12/2024	26.403	PROFIL PLUS	REPARATION DE ROUE
17/05/2024	12.195	CONTITRADE FRANCE	REMPLACEMENT PNEUS ETE