



FIAT DUCATO: FZ-505-BB

Vinnumber:	ZFA25000002R63349	Versionname:	FIAT DUCATO 2.3 Multijet 140 3.3 M H2 Pro Lounge VU [4P] bvm 6-140CH-8cv (fourgon tA'IA@simple cabine)
First Registrationdate:	4/05/2021	Fiscalpower:	103
Expertise Mileage:	999999	Power Kw:	White
Bodytype:	Transporter	Body colour:	Opaque
Gearbox:	MAN 6 VIT	Paint type:	Black
Transmission:	Front	Interior colour:	Steel
Fueltype:	Diesel	Type of rims (mounted):	Black
Engine functioning:	No	Dashboard color:	Black
Battery functioning:	No		
Vehicle running:	No		
Number of doors:	4		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Rear parking sensors	
GPS storage		Sliding door right-side	
GPS storage	HD	Seat cover lining	Lining Other
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Type of climate control	Manual climate control		

Tyres

215/70/15/109 Q				
Summer tyres:	Fr.L.	Michelin: 50%	Fr.R.	Michelin: 35%
	Re.L.	Michelin: 55%	Re.R.	Michelin: 40%
Tyre profile depth FL				5.0
Tyre profile depth FR				5.8
Tyre profile depth RL				4.6
Tyre profile depth RR				5.5
Tyre size FL				215/70 R 15 109 Q
Tyre size FR				215/70 R 15 109 Q
Tyre size RL				215/70 R 15 109 Q
Tyre size RR				215/70 R 15 109 Q
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	Yes	Jack	Yes
Remote ignition key, Missing, Repair/replace (lump sum)			



Interior, Stain, Cleaning



GPS, Missing, Replace



Wheel cover RL, Missing, Replace



Outside rear-view mirror base L, Scratch(es), Replace



Door FL, Scratch(es), Paint



Side panel L, Dent(s), Repair and paint (complete)



Door trim FL, Scratch(es), Replace



Bumper FL, Deformed / Strained, Replace





Bumper FR, Scratch(es), Dismount/Mount



Bumper grille, Broken, Replace



Sliding door R, Dent(s), Repair and paint (complete)



Side panel moulding R, Deformed / Strained, Replace



Car body corner RR, Dent(s) and scratch(es), Repair and paint (complete)



Side panel R, Dent(s), Repair and paint (complete)



Door FR, Scratch(es), Paint



Outside rear-view mirror base R, Broken, Replace



Side repeater R, Scratch(es), Replace



Outside rear-view mirror glass R, Broken, Replace



Wing FR, Scratch(es), Paint



Trunk door shutter, Missing, Replace



Trunk door stop button, Missing, Replace



Rear light L, Missing, Replace




Rear light R, Missing, Replace



Bumper R, Deformed / Strained, Replace



Parking sensor R, Broken, Replace



Parking sensor R, Broken, Replace



Bumper corner RR, Deformed / Strained, Repair and paint (complete)



Boot door panel RL, Dent(s), Repair and paint (complete)



Boot door lining R, Broken, Replace



Boot door lining R, Broken, Replace



Bodywork, Not original part, Remove lettering



Roof, cabin, Dent(s), Repair and paint (complete)



Historique Maintenance

Immatriculation: FZ-505-BB Date de 1ère immatriculation: 04/05/2021

Modèle: Fiat DUCATO 2.3 Multijet 140 3.3 M H2 Pro Lounge VU [4P] bvm 6-140CH-8cv (fourgon tôle simple cabine)

Date	Kilométrage	Fournisseur	Descriptif
23/06/2025	135.725	LA SQUADRA VELOCE	FERMETURE DOSSIER TECHNIQUE
	0		BATTERIE RPLT
	0		DIVERS ELEC
	0		FAISCEAU CABLAGE RPLT
12/02/2024	107.317	LA SQUADRA VELOCE	DIVERS ECHAPPEMENT
25/10/2023	98.502	LA SQUADRA VELOCE	LIQUIDE DE FREIN
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		BALAIS ESSUIE GLACE AV
07/10/2022	52.813	LA SQUADRA VELOCE	PLAQUETTES AV RPLT
	0		APPOINT D HUILE
12/05/2022	49.892	LA SQUADRA VELOCE	FERMETURE DOSSIER TECHNIQUE
	0		KIT DISTRIBUTION RPLT
	0		POMPE A EAU RPLT
19/04/2022	46.412	LA SQUADRA VELOCE	PLAQUETTES AR RPLT
	0		LAMPE AR RPLT
	0		BALAIS ESSUIE GLACE AV
	0		REVISION ET CLIM ET AIR ET CARBURANT
28/12/2021	31.730	EDR AUTOMOBILES	LAMPE RPLT