



<b>MINI 5D:</b>			
Vinnumber:	<b>WMWXU71050TV64233</b>	Versionname:	<b>Cooper (100 kW)</b>
First Registrationdate:	<b>12/12/2019</b>	Fiscalpower:	
Expertise Mileage:	<b>107565</b>	Power Kw:	<b>100</b>
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>3826</b>
Fueltype:	<b>Petrol</b>		
Maintenance:	<b>NOT OK</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>			
Number of keys total:	<b>2</b>	Sun Roof electric	
Cruise Control:		Panoramic roof	
Steering wheel multifunctional:		Luggage cover	
Seats F heated:		Rear parking sensors	
Radio multimedia:		Type of Tow bar:	<b>No Tow bar</b>
Type of headlighting:	<b>Headlighting LED</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining artificial leather</b>		
Type of climate control:	<b>Autom climate control</b>		

Limited Technical Inspection

Tyres

<b>205/45/17/92 H</b>				
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/45 R 17 92 H
Tyre size FR				205/45 R 17 92 H
Tyre size RL				205/45 R 17 92 H
Tyre size RR				205/45 R 17 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

Total cost ex VAT:	3418,81
Interior, Dirty, Cleaning:	175,04



Service, Maintenance, Check 0,00



Headlight R, Scratch(es), Polish 0,00



Windscreen, Stone chip(s), Windscreen repair 75,44



Wing RL, Dent(s) and scratch(es), Repair and paint (complete) 431,58



Alloy rim RL polished, Scratch(es), Repair and paint (complete) 204,21



Wing trim RL, Scratch(es), Replace 81,88



Door FL, Scratch(es), Acceptable 0,00



Outside rear-view mirror housing L, Scratch(es), Acceptable 0,00



Alloy rim FL polished, Scratch(es), Replace 471,41



Bumper R, Scratch(es), Repair and paint (complete) 296,58



Bumper trim R, Scratch(es), Acceptable 0,00



Rear window, Scratch(es), Replace 380,28



Tyre FR, Deformed / Strained, Replace 180,98



Alloy rim FR polished, Scratch(es), Replace 471,41



Wing trim FR, Scratch(es), Acceptable 0,00



Door FR, Scratch(es), Repair and paint (complete) 445,79



Door RR, Scratch(es), Acceptable 0,00



Alloy rim RR polished, Scratch(es), Repair and paint (complete) 204,21



Wing trim RR, Chemical polution, Acceptable 0,00



Door RR, Dent(s), Acceptable 0,00



Step R, Scratch(es), Acceptable 0,00

