

INSPECTION REPORT


End of contract


GENERAL INFO

File	312417
License plate	2AQL675
Vehicle identification number	VSSZZZKLZMR093464
Dossier	2021 070 048
Make	Seat Leon 1.4e PHEV 204 FR DSG
Mileage	84741
First registration	11/06/2021
client availability date	07/05/2026
inspectionDate	12/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	Y
18	Bumper Front / Spoiler / Replace	N
66	Wing Front Left // Polish	Y
196	Door Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	N
219	Door Front Right / Window / Replace	Y
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N

Damage Pictures



Wheel Alloy Rear Left // Repair-scratch



Wing Front Left // Polish-scratch




Wheel Alloy Front Left // Repair-scratch



Bumper Front // Polish-scratch




Bumper Front / Spoiler / Replace-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Door Front Right / Window / Replace-scratch



Wheel Alloy Front Right // Repair-scratch



Door Rear Right // Polish-scratch



Wheel Alloy Rear Right // Repair-scratch