



RENAULT CLIO: GD-095-LP

Vinnumber:	VF1RJA00368302773	Versionname:	RENAULT CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)
First Registrationdate:	9/12/2021	Fiscalpower:	
Expertise Mileage:	122048	Power Kw:	103
Bodytype:	Berline	Body colour:	White
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Petrol	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	2		
Type of rims (mounted):	Steel		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Headlights Xenon/LED/Laser	
Windows electric F		Rear parking sensors	
Cruise Control		Seat cover lining	Lining Other
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Manual climate control		

Tyres

	195/55/16/87 H			
Summer tyres:	Fr.L.	Bridgestone: 30%	Fr.R.	Bridgestone: 30%
	Re.L.	Firestone: 75%	Re.R.	Firestone: 75%
Tyre profile depth FL				6.2
Tyre profile depth FR				6.2
Tyre profile depth RL				3.5
Tyre profile depth RR				3.2
Tyre size FL				195/55 R 16 87 H
Tyre size FR				195/55 R 16 87 H
Tyre size RL				195/55 R 16 87 H
Tyre size RR				195/55 R 16 87 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				258
Tyre make RR				258

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Interior, Dirty, Cleaning



Headrest RR, Missing, Replace



Headrest RM, Missing, Replace



Headrest RL, Missing, Replace



Seat cover RL, Burned, Replace



Malfunction indicator, Blinking, Check



Tyre RL, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Bumper F, Broken, Replace and paint



Bumper moulding FR, Broken, Replace



Windscreen, Stone chip(s), Windscreen repair



Luggage compartment cover, Missing, Replace



Bumper R, Scratch(es), Paint



Bodywork, Not original part, Remove lettering



Historique Maintenance

Immatriculation: **GD-095-LP** Date de 1ère immatriculation: **09/12/2021**

Modèle: **Renault CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
24/02/2026	113.669	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
23/02/2026	113.668	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
15/12/2025	113.399	ETABLISSEMENTS MORALES	SERENITE
	0		LIQUIDE DE FREIN
	0		BALAIS ESSUIE GLACE AV
	0		DIVERS ECHAPPEMENT
07/03/2025	99.766	CHARENTE AUTOMOBILES DISTRIBUTION	JOINT DE COUVRE CULASSE RPLT
	0		BV COMPLETE RPLT
	0		MOTEUR RPLT
	0		DIVERS TRANSMISSION
	0		RECHARGE CLIM
	0		ESSAI
	0		DIVERS TRANSMISSION
	0		DIVERS ELEC
	0		DIVERS ECHAPPEMENT
	0		DIVERS MOTEUR
	0		HUILE BV RPLT
	0		DIVERS
	0		JOINT SPI ARBRE A CAMES RPLT
	0		BATTERIE RPLT
09/07/2024	89.046	CHARENTE AUTOMOBILES DISTRIBUTION	REVISION
12/04/2024	77.723	PROFIL PLUS	REPLACEMENT PNEUS ETE
23/06/2023	40.373	PROFIL PLUS	REPLACEMENT PNEUS ETE