



OPEL Corsa: 4094-LZX

Vinnumber:	VXKUPHNEKN4330817	Versionname:	1.2T XHL 74kW (100CV) Edition berlina con portón
First Registrationdate:	29/08/2022	Fiscalpower:	74kW 5P manual
Expertise Mileage:	47567	Power Kw:	
Bodytype:	Berline	Body colour:	Black
Gearbox:	MAN 5 VIT	Type of rims (mounted):	Aluminium
Transmission:			
Fueltype:	Petrol		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	No		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options

Number of keys total	2	Luggage cover
Number keys remote	1	
GPS big screen color		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of climate control	Manual climate control	

Tyres

195/55/16/87 H				
Summer tyres:	Fr.L.	Michelin: 8 mm	Fr.R.	Michelin: 8 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL				8.0
Tyre profile depth FR				8.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				195/55 R 16 87 H
Tyre size FR				195/55 R 16 87 H
Tyre size RL				195/55 R 16 87 H
Tyre size RR				195/55 R 16 87 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes
------------	------------

MOT certificate, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Door FL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Bumper F, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Door FR, Dent(s), Repair and paint (complete)



Outer door handle FR, Scratch(es), Paint



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Wing FR, Scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check

